

authors: State of New Mexico
 602 N. French Dr. Santa Fe, NM 87501
 Phone: (505) 241-7900

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name Solaris Water Midstream				API Number 30-085-44189			
Property Name Okeanos SWD #1				Well No. 1			

UL - Lot	Section	Township	Range	Foot from	NS Line	Foot from	EW Line	County
N	34	20S	34E	789	S	507	W	Lea

Surface Location

TAP WELL		SHUT-IN		INJECTOR		PRODUCER		DATE	
YES	NO	YES	NO	INJ	SWD	OIL	GAS	3-27-25	

OBSERVED DATA

	(A) Surface	(B) Interm	(C) Interm	(D) Prod. Cng	(E) Tubing
Pressure	0	0		0	2300
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Segment for
Water	Y/N	Y/N	Y/N	Y/N	Waterback if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION Entered into RBDMS Re-test	
Printed name:			
Title:			
E-mail Address:			
Date:	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 446907

CONDITIONS

Operator: SOLARIS WATER MIDSTREAM, LLC 9950 WOODLOCH FOREST DR THE WOODLANDS, TX 77380	OGRID: 371643
	Action Number: 446907
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/27/2026