

District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0220

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-02227	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No 064	

1. Surface Location									
UL • Lot M	Section 35	Township 17S	Range 34E		Feet from 660	N/S Line FSL	Feet From 660	E/W Line FWL	County LEA

Well Status									
YES	NO	YES	NO	INJ	INJECTOR	SWD	PRODUCER	GAS	DATE
									2-10-25

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	8			50	150
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Isjected for
Water	Y / N	Y / N	Y / N	Y / N	waterhead or

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>Joe mata</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Joe mata</i>		Entered into RBDMS	
Title <i>Lease Operator</i>		Re-test	
E-mail Address: <i>jmata@csfieldservices.com</i>			
Date <i>2-10-25</i>	Phone <i>6823524442</i>		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455796

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 455796
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/28/2026