

Southern District
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161

**State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRAUDENHEAD TEST REPORT**

DATA SHEET TEST REPORT	
Operator Name OCCIDENTAL PERMIAN LTD	API Number 30-025-07449
Property Name NORTH HOBBS G/SA UNIT	Well No. #121

Surface Location

UL-Lot	Section	Towship	Range		Feet From	N/S Line	Feet From	E/W Line	County
E	29	18S	38E		2310	FNL	330	FWL	LEA

Well Status

TAD Well	SHUT-IN	INJECTOR	PRODUCING	DATE
Yes	No	Yes	No	Inj. SWD OIL GAS 06/09/95

OBSERVED DATA

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Casing	(E) Tubing
Pressure	OPS1	OPS1	OPS1	375	390
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO ₂
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Water Flood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Gustavo Ramírez Berga, la 806-841-0566

Signature:			
Printed name:	Chance Huckaby		
Title:	Leader Well Surveillance		
E-mail Address:	Chance.Huckaby@oxy.com		
Date:	Phone:	(806) 894-0301	
	Witness:		

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 542289

CONDITIONS

Operator: OCCIDENTAL PERMIAN LTD P.O. Box 4294 Houston, TX 772104294	OGRID: 157984
	Action Number: 542289
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.trujillo	None	1/28/2026