District 1
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax. (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name		API Number
MORNINGSTAR OPERATING LLC		30-025-20236

Property Name		Well No
VACUUM GLORIETA WEST UNIT		085

Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
L	36	17S	34E		2180	FSL	660	FWL	LEA

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
(YES) NO	(YES) NO	INJ SWD	(OIL) GAS	2-12-25

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	N/A	N/A	0	none
Flow Characteristics					
Puff	Y /(N)	Y / N	Y / N	Y /(N)	CO2
Steady Flow	Y /(N)	Y / N	Y / N	Y /(N)	WTR __
Surges	Y /(N)	Y / N	Y / N	Y /(N)	GAS __
Down to nothing	(Y)/ N	Y / N	Y / N	(Y)/ N	Type of fluid Injected for Waterflood if applies
Gas or Oil	Y /(N)	Y / N	Y / N	Y /(N)	
Water	Y /(N)	Y / N	Y / N	Y /(N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

WELL IS TA

Signature		OIL CONSERVATION DIVISION
Printed name. Jesus Romero		Entered into RBDMS
Title Lease Operator		Re-test
E-mail Address: JRomero@Gfludsics.Com		
Date: 2-12-25 Phone 682-352-4714		
	Witness	

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 451180

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 451180
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/28/2026