

Southern District
1629 N French Dr, Hobbs, NM 88240
Phone: (505) 241-7063

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name Stephens & Johnson Operating Co.	API Number 300-25-05186
Property Name Denton North Wolfcamp Unit	Well No. Tract 5 No. 12

Surface Location									
UL - Lot E	Section 35	Township 14S	Range 37E		Foot from 1980	N/S Line North	Foot from 810	E/W Line West	County Lea

Well Status									
TAP WELL YES NO		SHUT-IN YES NO		INJECTOR INJ SWD		PRODUCER OIL GAS		DATE	

OBSERVED DATA

	(A) Surface	(B) Inter m (1)	(C) Inter m (2)	(D) Prod Casing	(E) Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 X WTR _____ GAS _____ Typical Fluid Indicates for or other fluids/ Liquids
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks-- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is P/A'd
10-17-2024

Signature		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title		Re-test	
E-mail Address			
Date	Phone		
	Witness		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 468734

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 468734
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	Status: Plugged (not released) Last Inspection: 12/16/2024	1/29/2026