

District I
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING, LLC		API Number 30-025-36681
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No 134

1. Surface Location									
UL - Lot K	Section 1	Township 18S	Range 34E		Feet from 2630	NS Line FSL	Feet From 1980	E/W Line FWL	County LEA

Well Status										
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 1 April

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	1080
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 X
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid subjected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature [Signature]		OIL CONSERVATION DIVISION
Printed name: Van R. P. Trower		Entered into RBDMS
Title LEADS BD		Re-test
E-mail Address: Trower@oilfieldsvcs.com		
Date: 1 April 25	Phone 505-491-9775	
Witness		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 461976

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 461976
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
rolando.chavarria	None	1/29/2026