

District 1
1625 N French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name		API Number
Seely Oil Company		30-025-37587
Property Name		Well No.
EK Queen Unit		#619

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
N	13	18S	33E		330	S	2310	W	Lea

Well Status

TA'D WELL	(NO)	SHUT-IN	(NO)	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
YES		YES		(INJ)					7-23-25


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csgn	(E)Tubing
Pressure	O	—	—	O	2150
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ✓
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS —
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	Mike Frazer		OIL CONSERVATION DIVISION
Printed name:			Entered into RBDMS
Title:			Re-test
E-mail Address:			
Date: 7-27-25	Phone:		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM



Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 489199

CONDITIONS

Operator: SEELY OIL CO 815 W 10th Street Ft. Worth, TX 76102	OGRID: 20497
	Action Number: 489199
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	1/29/2026