

District 1

1615 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0720State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-21031
Property Name VACUUM GLORIETA WEST UNIT		Well No 126

1. Surface Location									
UL - Lot E	Section 6	Township 18S	Range 35E		Feet from 1660	N/S Line FNL	Feet From 380	E/W Line FWL	County LEA

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	DATE 4-5-25

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	2	N/A	N/A	60	180
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR GAS Type of Fluid Injected for Waterflood if specifies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature 		OIL CONSERVATION DIVISION	
Printed name: Jeers Romero		Entered into RBDMS	
Title: Lease Operator		Re-test	
E-mail Address: JRomero@GulfSuds.com			
Date: 4-5-25	Phone: 505-352-4714		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 464774

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 464774
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
rolando.chavarria	None	1/30/2026