

District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0-20

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING, LLC	API Number 30-025-31809
Property Name VACUUM GLORIETA WEST UNIT	Well No 92

¹ Surface Location

UL - Lot L	Section 36	Township 17S	Range 34E	Feet from 1451	N/S Line FSL	Feet From 149	E/W Line FWL	County LEA


Well Status

YES	TA'D WELL NO	SHUT-IN NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 4-17-2025

OBSERVED DATA

	(A)Surface	(B)Interim(1)	(C)Interim(2)	(D)Prod CSDR	(E)Tubing
Pressure	0			0	50
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Field Injected for Waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature 	OIL CONSERVATION DIVISION
Printed name: E. Ray Camora	Entered into RBDMS
Title FSA	Re-test
E-mail Address ErayCamora@ctfield5VCS.com	
Date: 4-17-2025	Phone 682-478-6731
	Witness

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 464574

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 464574
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
rolando.chavarria	None	1/30/2026