

District I
1625 N French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Manning Star Operating LLC</i>	API Number <i>30-025-31840</i>
Property Name <i>Vacuum Gloria West Unit</i>	Well No. <i>#82</i>

* Surface Location

UL - Lot <i>I</i>	Section <i>36</i>	Township <i>15</i>	Range <i>34E</i>	Feet from <i>2526</i>	N/S Line <i>FSL</i>	Feet From <i>149</i>	E/W Line <i>FEL</i>	County <i>Lea</i>
----------------------	----------------------	-----------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL PRODUCER GAS	DATE <i>4-24-2025</i>
--	--	--	-----	---------------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	<i>0</i>			<i>0</i>	<i>920</i>
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Checked Prod. Casing
4-17-25-0
4-18-25-0
4-19-25-0 } *psi*
4-20-25-0

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: <i>Eloy Carmora</i>	Entered into RBDMS
Title: <i>FSA</i>	Re-test
E-mail Address: <i>Eduillon@ctfiel/svcs.com</i>	
Date: <i>4-24-2025</i>	Phone: <i>682-478-6731</i>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 464527

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 464527
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
rolando.chavarria	None	1/30/2026