

District I
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING, LLC		API Number 30-025-35562
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No 235

1. Surface Location									
UL - Lot H	Section 1	Township 18S	Range 34E	Feet from 2610	N/S Line FNL	Feet From 660	E/W Line FEL	County LEA	

Well Status										
YES	TA'D WELL ☒ NO	YES	SHUT-IN ☒ NO	☒ INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 2 April 25

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	1020
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Van Riper TB		OIL CONSERVATION DIVISION
Printed name Van Riper TIRONE		Entered into RBDMS
Title LEASE OP		Re-test
E-mail Address: Nanriper@CTF.cild sucs.com		
Date: 2 April 25	Phone: 505-471-9775	
Witness		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 462355

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 462355
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
rolando.chavarria	None	1/30/2026