

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Stephens + Johnson Operating Co.		API Number 30-015-02225
Property Name East Millman Pool Unit Tract 4		Well No 3

Surface Location

U/L - Lot 0	Section 12	Township 19S	Range 28E	Feet from 330	N/S Line FSL	Feet From 2278	E/W Line FEL	County Eddy
-----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	-----------------------

Well Status

TA'D Well YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> SWD	PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	DATE 7/29/2025
--	--	--	---	--------------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	880
Flow Characteristics					
Puff	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	CO2 _____
Steady Flow	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	WTR _____
Surges	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	GAS _____
Down to nothing	<input checked="" type="radio"/> Y <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	If applicable type
Gas or Oil	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	fluid injected for
Water	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

BHT- OK

REC'D AUG 04 2025

Signature: Mark C Hope		OIL CONSERVATION DIVISION
Printed name: Mark Hope		Entered RBDMS
Title: Pumper		Re-test
E-mail Address: hope-mark53@yahoo.com		
Date:	Phone: 575-748-5629	
	Witness: Ronald Hene	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 493033

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 493033
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	2/3/2026