

**District II – Artesia**  
 811 S. 1<sup>st</sup> Street, Artesia, NM 88210  
 Phone: (575) 748-1283 - Fax: (575) 748-9720

**State of New Mexico**  
**Energy, Minerals and Natural Resources Department**  
**Oil Conservation Division Artesia District Office**

**BRADENHEAD TEST REPORT**

Operator Name El Paso Natural Gas Company	3. API Number 30-015-20416
Property Name W.I. Federal - <i>Washington Ranch Storage Project</i>	Well No. #01

<sup>7</sup> Surface Location

UL - Lot <input checked="" type="checkbox"/>	Section 34	Township 25S	Range 24E	Feet from 1,650	N/S Line North	Feet From 1,650	E/W Line West	County Eddy
---	---------------	-----------------	--------------	--------------------	-------------------	--------------------	------------------	----------------

**Well Status**

TA'D Well YES	SHUT-IN <input checked="" type="checkbox"/>	INJECTOR <input checked="" type="checkbox"/>	PRODUCER OIL	GAS	DATE <i>7/1/2025</i>

**OBSERVED DATA**

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure		XXXXXXXXXXXXXX	XXXXXXXXXXXXXX		
Flow Characteristics					
Puff	<input checked="" type="checkbox"/> N	Y / N	Y / N	<input checked="" type="checkbox"/> N	CO2 _____
Steady Flow	<input checked="" type="checkbox"/> N	Y / N	Y / N	<input checked="" type="checkbox"/> N	WTR _____
Surges	<input checked="" type="checkbox"/> N	Y / N	Y / N	<input checked="" type="checkbox"/> N	GAS _____
Down to nothing	<input checked="" type="checkbox"/> N	Y / N	Y / N	<input checked="" type="checkbox"/> N	If applicable type
Gas or Oil	<input checked="" type="checkbox"/> N	Y / N	Y / N	<input checked="" type="checkbox"/> N	fluid injected for
Water	<input checked="" type="checkbox"/> N	Y / N	Y / N	<input checked="" type="checkbox"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Gas Storage Injection/Withdrawal Well. *BHT - OK*

*PRODUCTION CASING TOOK ABOUT 10 MINUTES TO BLOW DOWN TO NOTHING, THROUGH NEEDLE VALVE*  
*SURFACE CASING TOOK 1 MINUTE TO BLOW DOWN TO NOTHING.*

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
	Witness: <i>Braden Head</i>	

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 489520

**CONDITIONS**

Operator:  El Paso Natural Gas Company, L.L.C 1001 Louisiana Street Houston, TX 77002	OGRID: 7046
	Action Number: 489520
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
ronald.heuer	None	2/3/2026