

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Stephens + Johnson Operating Co.	API Number 30-015-10105
Property Name East Millman Pool Unit Tract 4	Well No 6

Surface Location									
U.L. - Lot N	Section 13	Township 19S	Range 28E		Feet from 990	N/S Line FSL	Feet From 1980	E/W Line FWL	County Eddy

Well Status				DATE
TA'D Well YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ SWD	PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	7/29/2025

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	560
Flow Characteristics					
Puff	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	CO2 _____
Steady Flow	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	WTR _____
Surges	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	GAS _____
Down to nothing	<input checked="" type="radio"/> Y / N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	<input checked="" type="radio"/> Y / N	If applicable type
Gas or Oil	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	fluid injected for
Water	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR <input type="checkbox"/>	FRESH <input type="checkbox"/>	SALTY <input type="checkbox"/>	SULFUR <input type="checkbox"/>	BLACK <input type="checkbox"/>
--------------------------------	--------------------------------	--------------------------------	---------------------------------	--------------------------------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

BHT - OK

REC'D AUG 04 2025

Signature: <i>Mark Hope</i>	OIL CONSERVATION DIVISION
Printed name Mark Hope	Entered RBDMS
Title: Pumper	Re-test
E-mail Address hope-mark53@yahoo.com	
Date:	Phone 575-748-5629
Witness <i>Gregory Lane</i>	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 493036

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 493036
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	3/20/2026