

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.	30-007-20529
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	VPR B
8. Well Number	63
9. OGRID Number	180514
10. Pool name or Wildcat	97047 Van Bremmer - Vermejo Gas

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Coalbed Methane

2. Name of Operator

EL PASO ENERGY RATON, L.L.C.

3. Address of Operator

PO BOX 190, RATON, NM 87740

4. Well Location

Unit Letter J : 1549 feet from the South line and 2390 feet from the East line  
Section 1 Township 29N Range 18E NMPM Colfax County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
8,060' (GL)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐ Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/03/05 Schlumberger ran Acoustic Cement Bond Log. TOC at 25'. ✓  
03/12/05 Schlumberger perf'd 1<sup>st</sup> stage - 2,237'-2,245' 32 Holes  
HES frac'd 1<sup>st</sup> stage - Pumped 593,401 scf 70 quality nitrogen foam with 48,853 lbs 16/30 brown sand at 22.1 bpm, ATP 2164 psi, ISIP 1,340 psi.  
Schlumberger perf'd 2<sup>nd</sup> stage - 1,237'-1,240', 1,280'-1,283', 1,301'-1,304', 1,319'-1,323' 52 Holes  
HES frac'd 2<sup>nd</sup> stage - Pumped 573,100 scf 70 quality nitrogen foam with 54,574 lbs 16/30 brown sand at 22.9 bpm, ATP 2207 psi, ISIP 1435 psi.  
Schlumberger perf'd 3<sup>rd</sup> stage - 1,054'-1,058', 1,085'-1,088' 28 Holes  
HES frac'd 3<sup>rd</sup> stage- Pumped 402,326 scf 70 quality nitrogen foam with 30,081 lbs 16/30 brown sand at 22.9 bpm, ATP 2,511 psi, ISIP 1,253 psi.  
03/24/05 Cleaned out well bore and pulled WRBPs.  
04/08/05 RIH tubing, rods and pump. Well is ready to be tested and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Shirley A Mitchell TITLE Regulatory Analyst DATE 04/25/05

Type or print name Shirley A Mitchell E-mail address: shirley.mitchell@elpaso.com Telephone No. (505) 445-6785  
For State Use Only

APPROVED BY: [Signature] TITLE DISTRICT SUPERVISOR DATE 5/5/05  
Conditions of Approval (if any):