

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-007-20556
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	VPR B
8. Well Number	69
9. OGRID Number	180514
10. Pool name or Wildcat	97047 Van Bremmer - Vermejo Gas

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Coalbed Methane	
2. Name of Operator EL PASO ENERGY RATON, L.L.C.	
3. Address of Operator PO BOX 190, RATON, NM 87740	
4. Well Location Unit Letter <u>H</u> : <u>1548</u> feet from the <u>North</u> line and <u>1233</u> feet from the <u>East</u> line Section <u>11</u> Township <u>29N</u> Range <u>18E</u> <u>NMPM</u> <u>Colfax</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 8,017' (GL)	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐ Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/04/05 Schlumberger ran Acoustic Cement Bond Log. TOC at 20'. ✓
03/18/05 Schlumberger perf'd 1st stage - 2,244'- 2,251' 28 Holes
HES frac'd 1st stage - Screened out with 1,347 lbs Brady sand in formation.
03/19/05 Re-Perf'd 1st stage - 2,244'- 2,248'
Re-Frac'd 1st stage - Screened out with 20,415 lbs Brady sand in formation
Schlumberger perf'd 2nd stage - 1,300'- 1,303', 1,279'- 1,281', 1,230'- 1,235', 1,212'- 1,215' 52 Holes
HES frac'd 2nd stage - Pumped 457,403 scf 70% quality nitrogen foam with 44, 040 lbs 16/30 brown sand at 20.9 bpm, ATP 2230 psi, ISIP 1627 psi.
Schlumberger perf'd 3rd stage - 784'- 789' 20 Holes
HES frac'd 3rd stage- Screened out with 1,897 lbs Brady sand in formation.
03/20/05 Re-frac'd 3rd stage - Pumped 18,756 scf 70% quality nitrogen. Screened out.
03/22/05 Coil tubing clean out of well bore. Pull plugs. Kill well.
04/21/05 Fished WRBP. Ran tubing, rods, and pump. Well is ready to be tested and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Shirley Mitchell TITLE Regulatory Analyst DATE 04/25/05

Type or print name Shirley A Mitchell E-mail address: Shirley.mitchell@elpaso.com Telephone No. (505) 445-6785

For State Use Only

APPROVED BY: [Signature] TITLE DISTRICT SUPERVISOR DATE 5/5/05

Conditions of Approval (if any)