

..Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-007-20588

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

VPR B

8. Well Number 94

9. OGRID Number 180514

10. Pool name or Wildcat 97047
Van Bremmer - Vermejo Gas

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Coalbed Methane

2. Name of Operator
EL PASO ENERGY RATON, L.L.C.

3. Address of Operator
PO BOX 190, RATON, NM 87740

4. Well Location
Unit Letter H : 1428 feet from the North line and 1177 feet from the East line
Section 21 Township 30N Range 18E NMPM Colfax County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
8,268' (GL)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work).
SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05/07/05 Schlumber ran Cement Bond Log. Cement to surface.

05/11/05 Schlumberger perf'd 1st stage - 2229'- 2235', 2237'- 2240', 2283'- 2290' 64 Holes
HES frac'd 1st stage - Pumped 678,273 scf 70% quality nitrogen foam with 20# Linear gel with 60,291 lbs 16/30 brown sand.
Schlumberger perf'd 2nd stage - 954'- 958', 960'- 963', 1048'- 1051' 40 Holes
HES frac'd 2nd stage - Pumped 361,896 scf 70% quality nitrogen foam with 20# Linear gel with 38,000 lbs 16/30 brown sand.
Schlumberger perf'd 3rd stage - 797'- 801', 835'- 839', 906'- 910' 48 Holes
HES frac'd 3rd stage - Pumped 448,605 scf 70% quality nitrogen foam with 20# Linear gel with 58,046 lbs 16/30 brown sand.

05/24/05 Clean out well bore. RIH tubing, rods and pump. Well is ready to be tested and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Shirley Mitchell TITLE Regulatory Analyst DATE 06/27/05
Type or print name Shirley A Mitchell E-mail address: shirley.mitchell@elpaso.com Telephone No. (505) 445-6785
For State Use Only

APPROVED BY: [Signature] TITLE DISTRICT SUPERVISOR DATE 7/12/05
Conditions of Approval (if any):