Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103 May 27, 2004											
District I District I District II District II District II	WELL API NO.											
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr	30-019-20134 5. Indicate Type of Lease											
1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505District IV	STATE FEE 6. State Oil & Gas Lease No.											
1220 S. St. Francis Dr., Santa Fe, NM 87505												
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	 Lease Name or Unit Agreement Name Hage & Webb Land & Cattle Co. 											
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Gas Well	8. Well Number Webb CD-1											
2. Name of Operator SWEPI LP	9. OGRID Number 250036											
3. Address of Operator P.O. Box 576, Houston, TX 77001	10. Pool name or Wildcat Wildcat											
4. Well Location												
Unit Letter N : 825+/- feet from the South line and 1815+/- Section 25 Township 11N Range 23E NMPM	feet from the West line County Guadalupe											
11. Elevation (Show whether DR, RKB, RT, GR, etc.,												
Pit or Below-grade Tank Application or Closure												
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance	e from nearest surface waterN/A											
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Constr	uction Material											
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data											
NOTICE OF INTENTION TO: SU	BSEQUENT REPORT OF:											
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WO	RK 🗌 ALTERING CASING 🗌											
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEI OTHER: OTHER:												
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates including estimated date											
 of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 1/6/12 Set 2 7/8 CIBP @ 9334'. Perf @ 9330' pump rate of ¼ bpm @ 1500psi. Perf 	tach wellbore diagram of proposed completion											
1/7/12 Sqz 55 sx cmt through perfs & disp to ctoc 6800' (taged @ 7944') pressure to												
1/9/12 Set CIBP @ 3300'. Perf @ 3250' sqz 77 sx cmt & disp to ctoc 3050' leaving 2 Pressure tested good @ 1500psi.	200' in 2 7/8, 5 ½, & 9 5/8 (Tag @ 2990')											
1/10/12 Set CIBP @ 1190' perf @ 1140' get pump rate all casing circ to pit. Sqz 145	sxs cmt & disp to ctoc 940' leaving											
200' in 2 7/8, 5 ½, 9 5/8, & 13 3/8 (Taged cmt @ 889') 1/11/12 Pressure test all casing strings for 30 min. (tested good) cut off well head & RIH w/lin & fill 5 ½ w/cmt from 30' &												
2 7/8, 9 5/8, 13 3/8 from 100' w/65 sxs cmt total.												
 1/12/12 Attempt to cap well, but well had bubbles. Weld on to 13 3/8 & shut in well. 2/3/12 Drill out 2 7/8 to 95' & tag next plug @ 885'. 	Monitor from 12 th to 31 st .											
2/5/12 Cut 2 7/8 @ 850' w/jet cutter attempt to pull pipe (not free)												
2/6/12Wash over 2 7/8 to 45'.Continued on next page.												
	· · · · · · · · · · · · · · · · ·											
I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines 🛛, a general permit 🗌												
SIGNATURETITLEP & A Supervisor (Basic	Energy Services) DATE 2-24-12											
Type or print name: E-mail address: For State Use Only	Telephone No. 432-563-3355											
	UPERVISOR DATE 1/23/2013											
APPROVED BY: <u>Provident Title</u> DIJINIUI J Conditions of Approval (if any):	UT LINYIUUN DATE //23/20/3											

•

, V 2/9/12 Cut 2 7/8 @ 300' & pull pipe out, cut 2 7/8 @ 798' pooh.

2/10/12 Set cmt rtnr in 5 1/2 @ 778' attempt pump rate pressure tested @ 800 psi. Spot 106' cmt on top of rtnr to ctoc 672'.

2/12/12 Start washing over 5 ½ drilling out cmt.

2/18/12 Continue washing over 5 ½ lost circulation pooh & noticed we split 5 ½ & 9 5/8 & knocked a hole in 13 3/8.

- 2/19/12 Tag cmt in 5 ½ @ 725'. Perf @ 700'. Perf @ 150'. Set cmt rtnr @ 675' sqz 370 sxs cmt sting out & circ 5 ½ cut @ 120'.
- 2/20/12 Tag cmt @ 118' perf @ 115'.
- 2/21/12 Set 5 ½ CIBP @ 100' spot 15 sxs cmt @ 100' to surface.
- 2/22/12 Check well for bubbles then Cut & Cap well.

					·										
Perry					· .	Mecha	anical Well SI	ketch						[2/12/12 5- 115 5 1/21 0 0
Mar-12									Webb CD # 1 Cuervo Field			-			2/19/12. Split 5 1/2" & 9 5/8" knocked hole in 13 AP/#: 30-019-2013
	 Casing	Depth (F	rom-To)	Size	Wt	Grade	Burst	Collapse	Collar	Drift	ID	bbl/ft	Hole	Mudj	3/8"trying to wash over. Tag cement inside 5 1/2" @ Comments
	Surf	0	1.216	13 3/8	54.5	. J-55	2730	1130		12.459	12.615	0.1546	17.5	8.3	725'. Perf at 700' and 150'. Set cement retainer at 675'. Bumped Plug, Floats Held, FL returns
CSG.					-			· · ·					-		Circ 70 bbls (371 sx of
	Prot	0	3,315	9 5/8"	,36	J55	3520	2020	STC	8.765	8.921	0.0773	12.25	8.7 WB	cement to surface. Pull up casing
	Prod	0	10,926 10,879	5-1/2" 2-7/8"	17 7.9	P-110 · 1,80	10640 13450	7460 13890	RTS-6	4.767 2.229	4 892 2.323	0.0232	7.875	13.5	w/10# mud. Tag cement
					a ii			1	lags in 51/2" casing.			o.132 at 1,190'.	Perf at		inside 5 1/2" @ 118'. Set 100' surface plu Perforate at 114'. Observe across all casing stri
TBG. Info.	Depth 10864'	Size 2 7/8"	Wt. 7.9#	Grade L80	Coupling RTS6	Drift 2.229"	Burst 13,450	Collapse 13,890	ID 2.323°	bbl/ft 0.00524	c 1140)'. Pump 1	45 sxs Cla		well. RIH and set CIBP at 30' plug inside 2 7/8
LNDG NIPPLE	Depth none	Size	MFG	TYPE	Profile ID	NO GO ID			PACKE			ppg ceme ent in 2 7/			H cement to surface.
Stage	Perf Top	Perf Bot	Shots	Sizua	्रान्छ (निर्धाननी सिन्दी)	Date Frac'ed	F.G.	- size	Proppant Informatio	un Lbs		X 9 5/8", /8" annulu			Tbg Spool: Note: Tubing hanger is prepared w/t Drilled out 2 7/8" and
12	9,462	9,464	12	OPEN	, 20	15-Feb-10	0,563	-	0	0	27/	8". Tag TO			washed over 2 7/8" X 5
	9,480 9,524	9,482 9,526	12				by TVD	30/50	Bulk Sand 30/50	165,000	insic	le 2 7/8".			1/2" cement and cut & pulled 2 7/8". Pulled 2
	9,533	9,535	12				<u> </u>		Pumped 500 gals of	7,5% HCI ahea	ad of breakdo	CIBP at 3,	300. Per	forate a	t 7/8" from ~798'. Set
11	9,584 9,601	9,586 9,603	12 12	OPEN	19	14-Feb-09	0.523 by TVD	- 30/50	0 Bulk Sand 30/50	0 130,000	Nov-09	3,250'. Pu 16.4 ppg -			H and pressure test. Teste
ļ	9,619 9,646	9,621 9,648	12 · 12	1			r		Pumped 500 gals of	7.5% HClobes	ad of breakdor	10 bbls u	o inside 5	5 1/2" X	9 7 1 106' of 16.4# Class H
10	9,682	9,648	12	OPEN	19	14-Feb-10	0 613			0	Nov-09	5/8" annu bbls insid			
F	9,715	9,717 9,734	12 12	ł			by TVD	30/50	Bulk Sand 30/50	255,000	·	(~200'). T 1/2" at 2,	ag cemei		
t	9,764	9,766	12	1					Dama 1 777	7.64 110		.,∠ dl∠,	. 000		TOC 2 7/8" 6730' per CE
9 [.]	9,837	9,839	12	OPEN	19	13-Feb-10	0.613		Pumped 500 gals of 0	7.5% HCI ahea	nd of breakdo Nov-09	4,630	Set CIE	SP @ 9,3	344' TOC 5-1/2"7600' per CBL
	9,847 9,864	9,849 9,866	12 12	1			by TVD	30/50	Bulk Sand 30/50	270,000			Squee	ze perfs pump 5	
ŀ	9,884	9,886	12	· ·									Class F	16.4 p	pg CIBP set at
8	9,902 9,941	9,904 9,943	12 12	OPEN	20	12-Feb-10	0.609		Pumped 500 gals of	7.5% HCI ahea	ad of breakdown Nov-09	4,696		t displa Is mud.	
Ů	9,950	9,952	12	OPEN	20	12-7-60-10	by TVD	30/50	Bulk Sand 30/50	181,000	1	4,090	TOC in	side 5 1	/2" at 5 BP set @ 9360'
ŀ	9,990 10,001	9,992 10,003	12 12	-									7,944'.		9/10
	10,017 10,030	10,019 10,032	12 12	1					Pumped 500 gals of	7 FW HClabor	4 vil of brookdow			1	Stage 11
7	10,059	10,071	12	OPEN	17	11-Feb-10	0.585	-	0	0	, Nov-09	4,765	186	ļ	
	10,094 10,104	10,096 10,106	12	1			by TVD	30/50	Bulk Sand 30/50	101,000	·				Stage 10
ļ	10,120	10,122	12	4	••										
	10,134 10,152	10,136	12 12					Went	Pumped 500 gals of to flush early due to risi			anned job		J	Stage 9
6	10,213	10,215 10,225	· 12 12	OPEN	20	10-Feb-10	0.607 by TVD	- 30/50	- Bulk Sand 30/50	0	Nov-09	4,843	187	-	
	10,257	10,259	12				5,175	56/50	Buk Band Subb	114,000					Stage 8
	10,266 10,278	10,268 10,280	12 12						Pumped 500 gals of	7.5% HCI ahea	ad of breakdowr	1]	Stage 7
5	10,334	10,336 10,344	12 12	OPEN	. 19	9-Feb-10	0.618	-	-	0	' Nov-09	4,908	189	r	
	10,342	10,344	12	.			by TVD	30/50	Bulk Sand 30/50	165,000	1				
4	10,396	10,398	12 12	OPEN	19	8-Feb-10	0.553		Pumped 500 gals of	7.5% HCl ahea	Nov-09	4,979	190	ļ	
	10,467	10,469	12	1			by TVD	30/50	Bulk Sand 30/50	78,500		7,010			Stage 5
ŀ	10,494 10,506	10,496 10,508	12 12						Pumped 500 gals of					1	Stage 4
3	10,535 10,572	10,537 10,574	12 12	OPEN	25	7-Feb-10	0.594	Went	to flush early due to risi	ng pressure - pl	laced 75% of pl Nov-09	anned job 5.048	191	ļ	
Ĩ	10,598	10,600	12	- CREW	25	, rep-10	by TVD	30/50	- Bulk Sand 30/50	69,200 [°]	1404-03	0,040	131		Stage 3
ŀ	10,623 10,632	10,625 10,634	12 12						Pumped 500 gais o						PBTD = 10,831/ (correlated)
<u> </u>	10,648 10,683	10,650 10,685	12 12	OPEN	24	6-Feb-10	0.57	Went	to flush early due to risi	ng pressure - pl	laced 71% of pl			ļ	Stage 2
2	10,694	10,696	12	OPEN	24	0-reb-10	0.64 by TVD	30/50	- Bulk Sand 30/50	0 111,500	Nov-09	5,106	192		BHT: 194 deg F (CBL) Stage 1
ŀ	10,704 10,724	10,706 10,726	12 12											F	FC: 10,879
	10,734 10,782	10,736 10,784	12 12	OREN	-00	5.5-6 10	0.611			~	N 22	E 450	400		T@10,864 (tally) TMD: 10,927' (dr/lij)
ť	10,801	10,803	12	OPEN	20	5-Feb-10	0.644 by TVD	30/50	- 8ulk Sand 30/50	0 136,000	Nov-09	5,150	193		5.1/2%17#s10.926'
	10,809	10,811	12					Went	to flush early due to risi	ng pressure - p	laced 95% of pl	anned job			- ·
				•									~		
							•.		5						
	,									•					
															· · ·
		, ·													
							·								



Shell Exploration & Production

State of New Mexico Energy, Minerals and Natural Resources Dept. Oil Conservation Division-District 4 1220 South St. Francis Drive Sante Fe, New Mexico 87505 Attn.: Ed Martin, District Supervisor

Shell Exploration & Production Co.

Regulatory Affairs-EP Americas 4582 S. Ulster Street Parkway Suite 1400 Denver, Colorado 80237

December 27, 2012

Subject: Subsequent Notice of Plugging and Abandonment Shell Exploration & Production Co., Webb CD-1 (API No. 30-019-20134) Guadalupe County, New Mexico

Dear Mr. Martin:

Shell Exploration & Production Company (Shell), as service provider to SWEPI LP in New Mexico, is submitting a Subsequent Notice of Plugging and Abandonment (Form C-103) to detail well plugging and abandonment activities conducted for the subject well, to New Mexico Oil Conservation Division-District 4 (OCD) for your review and approval.

If you have any questions or require any additional information regarding these reports, please contact me at (303) 222-6347, or Steve Compton at (303) 305-4017.

Regards,

Michael L. Bergstrom Senior Regulatory Advisor Shell Exploration & Production Company

Attachments: Form C-103 Mechanical Well Sketch