

District I 1625 N. French Dr., Hobbs, NM 88240
District II 1301 W. Grand Ave., Artesia, NM 88210
District III 1000 Rio Brazos Rd., Aztec, NM 87410
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

WELL API NO. 30-021-20592
5. Indicate Type of Lease STATE [] FEE [x]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Libby Minerals LLC 1931
8. Well Number 11-1-K
9. OGRID Number 251905
10. Pool name or Wildcat Bravo Dome 96010

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [] Other CO2 Well
2. Name of Operator Reliant Exploration & Production, LLC.
3. Address of Operator 10817 West County Road 60 Midland, TX 79707

4. Well Location Unit Letter K : 1720 feet from the South line and 1720 feet from the West line Section 11 Township 19 N Range 31 E NMPM County Harding

11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4523

Pit or Below-grade Tank Application [] or Closure []
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] MULTIPLE COMPL [] OTHER: []
SUBSEQUENT REPORT OF: REMEDIAL WORK [] ALTERING CASING [] COMMENCE DRILLING OPNS. [x] P AND A [] CASING/CEMENT JOB [x] OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [x], a general permit [] or an (attached) alternative OCD-approved plan [].

SIGNATURE [Signature] TITLE Manager DATE 2-3-14
Type or print name Vance Vandenberg E-mail address: vance@relimjases.com Telephone No. 432-555-7085

APPROVED BY: [Signature] TITLE DISTRICT SUPERVISOR DATE 2/13/2014
Conditions of Approval (if any):

Libby Minerals LLC 1931 11-1-K

1/22/14

MIRU Renegade Wireline. Perforate 2159' – 2178' @ 6 SPF. RD Renegade Wireline. MIRU Borderline Well Service. Swap fluid level down. MDRO Borderline Well Service.