

Worked on 06/12/2017



NMOCD

1000 Rio Brazos Road
Aztec, NM 87410

P.O. Box 1979, Farmington, NM 87499
(505) 325-2627

Name: Sofia #1
API:30-059-20486

Tower Report

Work Detail

6/12/17

Start	Stop	PUX	Activity
06:00 AM	07:00 AM	P	Ready equipment for road.
07:00 AM	05:00 PM	P	Road rig and support equipment to location.
05:00 PM	05:30 PM	P	Secure rig and equipment.
05:30 PM	06:30 PM	P	Travel to Clayton, NM.

* P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

Crew:

Title	Name	Hours	Vehicle
Supervisor:	Comanche, Dereck	12.50	60 - Crew PU
Operator:	Fasthorse, Toby	12.50	63 - Crew PU
Derrick:	Valencia, Ivan	12.50	

On Site Reps:

Name	Association	Notes
Ameino Martinez	Other	12.5 Hrs.
Rio Escojeda	Other	12.5 Hrs.

Worked on 06/13/2017



NMOCD

1000 Rio Brazos Road
Aztec, NM 87410

P.O. Box 1979, Farmington, NM 87499
(505) 325-2627

Name: Sofia #1
API:30-059-20485

Well Plugging Report

Work Detail

Start	Stop	PUX	Activity
05:30 AM	07:00 AM	P	Travel to loc.
07:00 AM	07:30 AM	P	HSM on JSA. Service and start equipment.
07:30 AM	12:00 PM.	P	Check well PSI: No tbg, Csg 20 PSI, BH 0 PSI. RU daylight pulling unit. NU A Plus 4-1/2" WH to master valve NU BOP. preform function test. RU relief blow down well work floor, Tbg equip. RU pump and cmt. equipment.
12:00 PM	02:00 PM	P	Tally A Plus 2-3/8" W.S., PU A Plus string mill TIH w/ 64 jnts to 2020', LD 1 jnt TOO H w/ 63 jnts, LD string mill.
02:00 PM	03:30 PM	X	PU A Plus 4.5" CR TIH w/ 63 jnts PU 16' subs set CR at 2000' PT tbg to 1000 PSI, Release CR, Pump and attempt establish circ. w/ 35 bbl no circ, Sting into CR pump and attempt est. rate bbl a min at PSI. (Windy cond.)
03:30 PM	04:00 PM	P	P #1 (Yeso)M & P 45 sks 53.1 cf 15.6 PPG Class B Cmt. from 2132' to 2000'. After M & P cmt 5 bbl into disp. tbg locked attempt squeeze, Sting out CR attempt work PSI free PSI not bleed off hold 1000 psi. relive PSI. W/ 10 Below and 18 out.
04:00 PM	06:30 PM	X	LD 16' subs, LD 33 jnts found cmt est 17 sks in tbg LD total 63 jnts found plugged off in setting tool. Clean out cmt'd jnts clean equipment. Clean out setting tool. SIW secure loc. SDFD.
06:30 PM	07:30 PM	P	Travel back to Clayton.

* P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

Comments

Job	Comment
P #1	(Yeso)M & P 45 sks 53.1 cf 15.6 PPG Class B Cmt. from 2132' to 2000'. After M & P cmt 5 bbl into disp. tbg locked attempt squeeze, Sting out CR attempt work PSI free PSI not bleed off hold 1000 psi. relive PSI. W/ 10 Below and 18 out.

Crew:

Title	Name	Hours	Vehicle
Derrick:	Escojeda, Rio	14.00	
Floor	Martinez, Amineo	14.00	
Floor	Valencia, Ivan	14.00	
Operator:	Fasthorse, Toby	14.00	63 - Crew PU
Supervisor:	Comanche, Dereck	14.00	60 - Crew PU

Worked on 06/14/2017



NMOCD

1000 Rio Brazos Road
Aztec, NM 87410

P.O. Box 1979, Farmington, NM 87499
(505) 325-2627

Name: Sofia #1
API:30-059-20485

Well Plugging Report

Work Detail

Start	Stop	PUX	Activity
05:30 AM	07:00 AM	P	Travel to loc.
07:00 AM	07:30 AM	P	HSM on JSA. Service and start equipment.
07:30 AM	08:00 AM	P	Check well No Tbg, Csg 20 PSI, BH 0, RU relief line attempt blow down well would not blow down, RU pump to csg pump 10 bbls fresh water kill well.
08:00 AM	10:00 AM	X	PU tag sub TIH w/ 64 jnts tag up at 1990' LD 1 jnts PU 10' sub EOT at 1990', RU pump to tbg pump and attempt est. circ. w/ 35 bbl no circ. Pre mix 1% cal. chlor. for 90 sks.
10:00 AM	10:30 AM	X	P #1A () M & P 90 sks w/ 1% cal. chlor. 106.2 cf 15.7 ppg Class B Cmt from 1990'to unknown. While csg valve shut entire plug. No PSI.
10:30 AM	02:30 PM	X	LD 10' sub and 63 jnts, LD setting tool. WOC per sample.
02:30 PM	06:30 PM	X	PU 4' tag TIH w/ 44 jnts tag @ 1363' tag good LD 4 jnts, TOOH W/ 40 jnts LD tag sub, PU A Plus 4.5" string mill TIH w/ 40 jnts PU 1 jnt, LD 1 jnt EOT @ 1257' TOOH LD string mill, PU 4.5" A Plus CR TIH set CR @ 1257' release off CR, RU pump to tbg pump and est circ. w/ 20 bbl pump total 25 bbl total. PT csg to 800 PSI for 30 min PT good. SIW secure loc. SDFD.
06:30 PM	07:30 PM	P	Travel to Hotel.

* P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

Comments

Job	Comment
P# 1A	() M & P 90 sks w/ 1% cal. chlor. 106.2 cf 15.7 ppg Class B Cmt from 1990'to unknown. While csg valve shut entire plug. No PSI.

Crew:

Title	Name	Hours	Vehicle
Derrick:	Escojeda, Rio	14.00	
Floor	Martinez, Amineo	14.00	
Floor	Valencia, Ivan	14.00	
Operator:	Fasthorse, Toby	14.00	62 - Crew PU
Supervisor:	Comanche, Dereck	14.00	60 - Crew PU

Equipment:

#625 lgr. - WASTE PITS

Worked on 06/15/2017



NMOCD

1000 Rio Brazos Road
Aztec, NM 87410

P.O. Box 1979, Farmington, NM 87499
(505) 325-2627

Name: Sofia #1
API:30-059-20485

Well Plugging Report

Work Detail

Start	Stop	PUX	Activity
07:30 AM	09:00 AM	P	Travel to location
09:00 AM	09:30 AM	P	HSM on JSA. Service equipment.
09:30 AM	10:00 AM	P	Check well PSI: 0 PSI Tbg, 0 PSI Csg, 0 PSI BH. RU relief open to pit.
10:00 AM	10:30 AM	P	RU pump to tbg, Sting into CR pump and est. injection rate of 3 bbl a min at 300 PSI.
10:30 AM	11:30 AM	P	P #2 (Santa Rosa) M & P 80 sks 94.4 cf 15.6 PPG Class B Cmt. from 1466' to 1098' toc. w/ 16 below 12 above 52 out
11:30 AM	12:00 PM	P	LD 12 jnts EOT at 859', Pump and est. circ. w/ 1 bbl.
12:00 PM	12:30 PM	P	P #3 (Sur. csg Shoe, Chinle, Exeter) M & P 20 sks 23.6 cf 15.7 PPG Class B Cmt from 859' to 595' toc.
12:30 PM	01:30 PM	P	LD 28 jnts, LD setting tool, PU 8 jnts EOT at 252', Pump and est. circ. w/ 1.5 bbl.
01:30 PM	02:00 PM	P	P #4 (Surface) M & P 28 sks 33.04 cf 15.7 PPG Class B Cmt. from 252' to 0' good cmt. returns out csg
02:00 PM	07:00 PM	P	LD 8 jnts RD tbg equip. RD workfloor, ND BOP dig out WH Preform hot work permit cut WH cmt. at surface in csg and 60' down on back side Install DHM M & P 24 sks to set DHM, RD pump and cmt. equip., RD daylight pulling unit clean and secure loc. Ready to MOL in am.
07:00 PM	08:00 PM	P	Travel to Hotel

* P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

Comments

Job	Comment
P #2	(Santa Rosa) M & P 80 sks 94.4 cf 15.6 PPG Class B Cmt. from 1466' to 1098' toc. w/ 16 below 12 above 52 out
P #3	(Sur. csg Shoe, Chinle, Exeter) M & P 20 sks 23.6 cf 15.7 PPG Class B Cmt from 859' to 595' toc.
P #4	(Surface) M & P 28 sks 33.04 cf 15.7 PPG Class B Cmt. from 252' to 0' good cmt. returns out csg
DHM	M & P 24 sks to set DHM

Crew:

Title	Name	Hours	Vehicle
Derrick:	Escojeda, Rio	12.50	
Floor	Chavez, Billy	8.00	
Floor	Valencia, Ivan	12.50	

Operator: Fasthorse, Toby 12.50
Supervisor: Comanche, Dereck 12.50

Worked on 06/15/2017
62 - Crew PU
60 - Crew PU

On Site Reps:

Name	Association	Notes
Billy Chavez	Other	Start time at 10 A.M.

Equipment:

#625 lgr. - WASTE PITS

Worked on 06/23/2017



NMOCD
1000 Rio Brazos Road
Aztec, NM 87410

P.O. Box 1979, Farmington, NM 87499
(505) 325-2627

Name: Sofia #1
API:30-059-20485

Well Plugging Report

Work Detail

Start	Stop	PUX	Activity
06:30 AM	08:00 AM	P	Travel to location.
08:00 AM	08:30 AM	P	HSM on JSA. Service and start equipment. update logs.
08:30 AM	05:00 PM	P	Road rig and equipment back to A Plus yard Farmington NM.

* P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

Crew:

Title	Name	Hours	Vehicle
Derrick:	Abeyta, Sean	10.50	
Floor	Escojeda, Rio	10.50	
Floor	Valencia, Ivan	10.50	
Operator:	Fasthorse, Toby	10.50	62 - Crew PU
Supervisor:	Comanche, Dereck	10.50	60 - Crew PU