Submit 3 Copies To Appropriate District	State of New Mexic	o Form C-103
Office District I	Energy, Minerals and Natural	Resources May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION D	VISION 30-007-20859
District III	1220 South St. Francis	7. Indicate Type of Lease Dr. STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8750	7. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	7. State Off & Gas Ecase 140.
87505	ICEG AND DEPONTS ON WELLS	
	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG I	7. Lease Name or Unit Agreement Name
	CATION FOR PERMIT" (FORM C-101) FOR S	
PROPOSALS.)		0 11/11/1 1 220
	Gas Well Other Coalbed Meth	ine
2. Name of Operator	OF & D COMPANY I D	9. OGRID Number
EL PASO E & P COMPANY, L.P.  3. Address of Operator		10. Pool name or Wildcat
•	190, RATON, NM 87740	10. I out hante of Wildean
4. Well Location	,	
	3 fact from the North line and	1341 feet from the West line
Section 20 Towns	hip 31N Range 21E 11. Elevation (Show whether DR, RE	NMPM Colfax County
U .	7, 879' (G	
Pit or Below-grade Tank Application . c	r Closure	<u></u>
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil		<b>,</b>
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☒ P AND A		
	1	ASING/CEMENT JOB
	_	_
OTHER:		THER:
		nent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion
or recompletion.		
or recompletion.		
07/13/07 Spud @ 1:15 p.m. Drill 11" surface hole to 320'. Run 8 jts. of 8 5/8", 24#, J55 ST & C casing at 311'.		
Halliburton mixed and pumped 100 sks Midcon II cement. Circulated 7 bbls of cement to surface.		
WOC 8 hrs. Test surf	ace 8 5/8" csg to 500 psi for 30 minut	es.
07/14/07 Duill 7 7/92 hala from	220' 2180' Darah J.TD -42180	0-4 11.45
07/14/07 Drill 7 7/8" hole from 320' - 2180'. Reached TD at 2180' at 11:45 a.m.  MIRU Superior and log well. Logger's TD 2181'.		
	of, J-55, and 9 jts 17 ppf, J-55 LT&C ca	sing st 2150
		circulate to pit. Prep for remedial cement squeeze job.
I hereby certify that the information	above is true and complete to the best of	f my knowledge and belief. I further certify that any pit or below-
grade tank has been/will be constructed or	<i>A</i> .	general permit 🗌 or an (attached) alternative OCD-approved plan 🗌.
SIGNATURE Shirle	Pritchell TITLE Re	gulatory Analyst DATE 07/18/2007
Type or print name Shirley A. Ma		mitchell@elpaso.com Telephone No. (505) 445-6785
For State Use Only		
1// -	$\mathcal{M} \mathcal{L}$ : $N$	STRICT SUPERVISOR DATE 2/32/02
APPROVED BY:	//cirtus TITLE	OINIOI OUPLNATOUN DATE 7/27/07
Conditions of Approval (if any):	/	/ /