

Submit To Appropriate District Office State Lease - 6 copies Fee Lease - 5 copies District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED		Form C-105 Revised June 10, 2003	
		WELL API NO.		30-007-20777	
		5. Indicate Type of Lease		STATE ☐ FEE ☒	
		State Oil & Gas Lease No.			
WELL COMPLETION OR RECOMPLETION REPORT AND LOG					
1a. Type of Well: OIL WELL ☐ GAS WELL ☒ DRY ☐ OTHER <u>Coalbed Methane</u>			7. Lease Name or Unit Agreement Name VPR B		
b. Type of Completion: NEW ☒ WORK ☐ DEEPEN ☐ PLUG ☐ DIFF. WELL OVER BACK RESVR. ☐ OTHER					
2. Name of Operator EL PASO E & P COMPANY, L.P.			8. Well No. 154		
3. Address of Operator PO BOX 190 RATON, NEW MEXICO 87740			9. Pool name or Wildcat Van Bremmer - Vermejo Gas		
4. Well Location Unit Letter <u>D</u> : <u>1151</u> Feet From The <u>North</u> Line and <u>474</u> Feet From The <u>West</u> Line Section <u>20</u> Township <u>29N</u> Range <u>19E</u> NMPM Colfax County					
10. Date Spudded 03/07/2007		11. Date T.D. Reached 03/08/2007		12. Date Compl. (Ready to Prod.) 06/11/2007	
				13. Elevations (DF& RKB, RT, GR, etc.) 7,854'	
14. Elev. Casinghead 7,854'					
15. Total Depth 2,215'		16. Plug Back T.D. 2,297'		17. If Multiple Compl. How Many Zones?	
				18. Intervals Drilled By 0 - TD	
				19. Producing Interval(s), of this completion - Top, Bottom, Name 951' - 2,177' Raton - Vermejo Coals	
				20. Was Directional Survey Made	
				21. Type Electric and Other Logs Run Compensated Density Single Induction Log and Cement Bond Log	
				22. Was Well Cored No	
23. CASING RECORD (Report all strings set in well)					
CASING SIZE	WEIGHT LB./FT.	DEPTH SET	HOLE SIZE	CEMENTING RECORD	AMOUNT PULLED
8 5/8"	23 lbs	307'	11"	100 sks	
5 1/2"	15.5 lbs	2,298'	7 7/8"	328 sks	
24. LINER RECORD			25. TUBING RECORD		
SIZE	TOP	BOTTOM	SACKS CEMENT	SCREEN	SIZE
					2 7/8"
					2,223'
26. Perforation record (interval, size, and number)			27. ACID, SHOT, FRACTURE, CEMENT, SQUEEZE, ETC.		
2166'- 2169', 2173'- 2177' 28 Holes 1928'- 1931', 1963'- 1969' 36 Holes 1682'- 1684', 1716'- 1718', 1724'- 1726', 1739'- 1742', 1745'- 1748', 1757'- 1760' 60 Holes 951'- 953', 959'- 961', 978'- 980', 996'- 998', 1005'- 1007' 40 Holes			DEPTH INTERVAL 951' - 2,177' AMOUNT AND KIND MATERIAL USED 94,752 lbs 20/40 mesh sand 1,578,167 scf 70% quality Nitrogen w/ Linear gel		
28. PRODUCTION					
Date First Production 07/06/2007		Production Method (<i>Flowing, gas lift, pumping - Size and type pump</i>) Pumping water up 2 7/8" tubing, insert pump and 2' x 1 1/4" x 10' Pumping unit. Flowing gas up 5 1/2" casing.		Well Status (<i>Prod. or Shut-in</i>) Production	
Date of Test 07/06/2007	Hours Tested 24 Hours	Choke Size Full 2"	Prod'n For Test Period	Oil - Bbl N/A	Gas - MCF 0
				Water - Bbl. 0	Gas - Oil Ratio N/A
Flow Tubing Press. 0 psi	Casing Pressure 0 psi	Calculated 24-Hour Rate	Oil - Bbl. N/A	Gas - MCF 0	Water - Bbl. 0
					Oil Gravity - API - (<i>Corr.</i>) N/A
29. Disposition of Gas (<i>Sold, used for fuel, vented, etc.</i>) Sold, used for fuel.					Test Witnessed By Lyn Essman
30. List Attachments					
31. I hereby certify that the information shown on both sides of this form as true and complete to the best of my knowledge and belief					
Signature <i>Shirley A. Mitchell</i>		Printed Name Shirley A. Mitchell		Title Regulatory Analyst	Date 08/20/2007
E-mail Address shirley.mitchell@elpaso.com					

4

Southeastern New Mexico	Northwestern New Mexico
-------------------------	-------------------------

OIL OR GAS SANDS OR ZONES

No. 3, from.....to.....

No. 4, from.....to.....

tion to which water rose in hole.

No. 1, from.....to.....

No. 2, from.....to.....feet.....

LITHOLOGY RECORD (Attach additional sheet if necessary)

Lithology	From	To	Thickness
-----------	------	----	-----------

From	To	Thickness In Feet	Lithology

From	To	Thickness In Feet	Lithology