

..Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
2008 APR 7 PM 3 38

WELL API NO.

30-007-20185

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

VPR B

8. Well Number 5

9. OGRID Number 180514

10. Pool name or Wildcat

Van Bremmer - Vermejo Gas

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Coalbed Methane

2. Name of Operator

EL PASO E & P COMPANY, L.P.

3. Address of Operator

PO BOX 190, RATON, NM 87740

4. Well Location

Unit Letter **K** : **1615** feet from the **South** line and **1403** feet from the **West** line  
Section **35** Township **30N** Range **18E** **NMPM** **Colfax** County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

8,290' (GL)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER RECOMPLETION ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work).  
SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03/04/08 MIRU Bronco. PU Rods, Tubing, Production Equipment.

03/21/08 MIRU Weatherford and Halliburton and Perforate and Stimulate the following Raton Coal Intervals:

Stage 1 - 2064'- 2067', 2092'- 2095', 2107'- 2110', 2152'- 2155' 48 Holes

Pump 4612,878 scf, 70% Quality Nitrogen foam with 40,373 lbs 20/40 mesh sand.

Stage 2 - 1374'- 1378', 1456'- 1459' 28 Holes

Pump 389,378 scf, 70% Quality Nitrogen foam with 23,134 lbs 20/40 mesh sand.

Stage 3 - 1166'- 1172', 1246'- 1251', 1294'- 1302' 88 Holes

Pump 483,774 scf, 70% Quality Nitrogen foam with 38,959 lbs 20/40 mesh sand.

Stage 4 - 914'- 918', 926'- 932', 996'- 1000' 56 Holes

Pump 309,770 scf, 70% Quality Nitrogen foam with 20,710 lbs 20/40 mesh sand.

04/02/08 MIRU Completion Unit. Clean hole out to PBTD 2,715'.

04/03/08 Run pump, tubing, and rods.

04/04/08 Test well and put back on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Shirley Mitchell TITLE Regulatory Analyst DATE 04/04/2008

Type or print name Shirley A Mitchell E-mail address: shirley.mitchell@elpaso.com Telephone No. (505) 445-6785

For State Use Only

APPROVED BY: Ed Martin TITLE DISTRICT SUPERVISOR DATE 4/9/08

Conditions of Approval (if any):