

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO. 30-007-20836

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

VPR A

8. Well Number 259

9. OGRID Number 180514

10. Pool name or Wildcat
Stubblefield Canyon - Vermejo Gas

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well ☒ Other Coalbed Methane

2. Name of Operator

EL PASO E & P COMPANY, L.P.

3. Address of Operator

PO BOX 190, RATON, NM 87740

4. Well Location

Unit Letter G : 1781 feet from the North line and 1421 feet from the East line

Section 30 Township 31N Range 20E NMPM Colfax County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

8,236' (GL)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/13/08 Superior ran Cement Bond Log. Estimated top of cement at surface.

04/23/08 Weatherford Wireline perf'd 1st stage - 1980'- 1985', 1981'- 1984' 12 Holes

HES frac'd 1st stage - Pumped 391,200 scf 70% quality nitrogen foam with 25# linear gel and 6,017 lbs 20/40 mesh sand.

Perf'd 2nd stage - 1683'- 1687', 1739'- 1742' 28 Holes

Frac'd 2nd stage - Pumped 354,208 scf 70% quality nitrogen foam with 25# linear gel and 13,574 lbs 20/40 mesh sand.

Perf'd 3rd stage - 1117'- 1121', 1156'- 1159', 1203'- 1209' 52 Holes

Frac'd 3rd stage - Pumped 291,706 scf 70% quality nitrogen foam with 25# linear gel and 37,098 lbs 20/40 mesh sand.

Perf'd 4th stage - 880'- 883', 891'- 896', 952'- 954', 1002'- 1008' 64 Holes

Frac'd 4th stage - Pumped 371,305 scf 70% quality nitrogen foam with 25# linear gel with 37,051 lbs 20/40 mesh sand.

04/26/08 Coil tubing clean out.

04/28/08 RIH tubing, rods and pump. Well is ready to be tested and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Shirley Mitchell TITLE Regulatory Analyst DATE 08/04/2008

Type or print name Shirley A Mitchell E-mail address: shirley.mitchell@elpaso.com Telephone No. (505) 445-6785

For State Use Only

APPROVED BY: Ed Martin TITLE DISTRICT SUPERVISOR DATE 8/13/08

Conditions of Approval (if any):