

Submit 1 Copy to Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-007-20891
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name VPR A
8. Well Number 311
9. OGRID Number 180514
10. Pool name or Wildcat Stubblefield Canyon Raton-Vermejo Gas

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other CBM	
2. Name of Operator El Paso E&P Company, L.P.	
3. Address of Operator 1001 Louisiana, Rm 9.028TP, Houston, TX 77002	
4. Well Location Unit Letter <u>L</u> : <u>1982</u> feet from the <u>South</u> line and <u>317</u> feet from the <u>West</u> line Section <u>26</u> Township <u>31N</u> Range <u>20E</u> NMPM County <u>COLFAX</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 7930' (GL)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Reperf'd & Frac'd ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08/03/10: MIRU. Tested tubing to 3000#. ND WH & NU 3000# WH. SDFN.

08/04/10: Perf'd 1859'-1863', 1877'-1879', 1887'-1889', 1894'-1904' (added 2' of perf's 1902'-1904'). Set packer @ 1830'. NU and tested wk string to 4000#. Good test. ND kill truck. NU frac valve. RDMO.

08/24/10: Pumped 400 gals acid 7.5% HCL. Pumped 40/70 sand slugs. Pumped 39.5# 16/30 (total). Flushed with 35 solu balls. Pumped 400 gals of acid 7.5% HCL. Flushed. Pumped 3.5# 16/30 (total). Flushed.

08/28/10: ND frac valve. ND 3000# WH. NU production WH. NU BOP. TOOHH and LD WS & packer. Broke circulation and cleaned to PBTB 2075'. ND BOP.

08/30/10: Inserted pump and rods. RDMO.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria S. Gomez TITLE Sr. Regulatory Analyst DATE 12/01/10

Type or print name Maria S. Gomez E-mail address: maria.gomez@elpaso.com PHONE: 713-420-5038/832-683-0361 cell  
**For State Use Only**

APPROVED BY: Ed Martin TITLE **DISTRICT SUPERVISOR** DATE 12/7/2010  
Conditions of Approval (if any):