


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nmcb1121351343* *229137* **OPERATOR** ☒ Initial Report ☒ Final Report



Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #102	Facility Type	Salt Water Disposal
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-21398

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	26S	28E					Eddy

Latitude 32 02.649 Longitude 104 05.441

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	19bbls
Source of Release	Produced water tank	Date and Hour of Occurrence	06/16/2011	Date and Hour of Discovery	06/16/2011 12:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Due to maintenance at the other disposals, this disposal was receiving more water than normal causing the release.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls of produced water was released from the produced water tank inside the dike walls of the SRO SWD #102. We were able to recover 19bbls of water with a vacuum truck and the entire release was contained inside the lined facility. All free fluid has been removed; the facility has been washed/cleaned and returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Approved by District Supervisor: 			
Title: HSE Coordinator		Approval Date: 8/1/2011		Expiration Date: NA	
E-mail Address: jrusso@conchoresources.com		Conditions of Approval: NA		Attached <input type="checkbox"/>	
Date: 07/01/2011 Phone: 432-212-2399		<i>Approved as Final Report</i>			

\* Attach Additional Sheets If Necessary

2RP-804

## **Bratcher, Mike, EMNRD**

---

**From:** Joshua Russo [jrusso@conchoresources.com]  
**Sent:** Friday, July 01, 2011 10:02 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** C-141 Initial / Final Report - SRO SWD #102 (Lined Facility)  
**Attachments:** SRO SWD #102 LINED FACILITY -- DATE OF RELEASE -- 06-16-2011.pdf

Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at the SRO SWD #102 on 06/16/2011. This is a lined facility.

Have a great holiday weekend!

Thanks,

### **Joshua Russo**

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.