

☐ USDOT Number ☐ MC/MX Number ☒ Name

Enter Value:

Company Snapshot

AFTERMATH HOT OIL SERVICES LLC

USDOT Number: 3598466

ID/Operations | [Inspections/Crashes In US](#) | [Inspections/Crashes In Canada](#) | [Safety Rating](#)

Carriers: If you would like to update the following ID/Operations information, please complete and submit form [MCS-150](#) which can be obtained [online](#) or from your State FMCSA office. If you would like to challenge the accuracy of your company's safety data, you can do so using FMCSA's [DataQs](#) system.

Other Information for this Carrier

▼ [SMS Results](#)

▼ [Licensing & Insurance](#)

USDOT Status

- **ACTIVE:** The entity's US DOT number is active.
- **INACTIVE:** Inactive per 49 CFR 390.19(b)(4); biennial update of MCS-150 data not completed.
- **OUT-OF-SERVICE:** Carrier is under any type of out-of-service order and is not authorized to operate.

Operating Authority Status

- **AUTHORIZED FOR { Passenger, Property, HHG }:** This will list the specific operating authorities the carrier (or broker) is allowed to operate.
- **NOT AUTHORIZED:** The entity does not have any operating authority and/or is not authorized to engage in interstate, for-hire operations
- **OUT-OF-SERVICE:** Carrier is under any type of out-of-service order and is not authorized to operate.

Out of Service Date

Indicates the date the company was ordered Out of Service. If there are multiple Out of Service orders, the earliest date will be displayed.

Please note: If there are multiple Out-of-Service orders, the earliest date will be displayed.

For help on the explanation of individual data fields, click on any field name or for help of a general nature go to [SAFER General Help](#).

The information below reflects the content of the FMCSA management information systems as of **04/15/2024**.

USDOT INFORMATION			
<u>Entity Type:</u>	CARRIER		
<u>USDOT Status:</u>	ACTIVE	<u>Out of Service Date:</u>	None
<u>USDOT Number:</u>	3598466	<u>State Carrier ID Number:</u>	
<u>MCS-150 Form Date:</u>	01/25/2024	<u>MCS-150 Mileage (Year):</u>	10,000 (2023)
OPERATING AUTHORITY INFORMATION			
<u>Operating Authority Status:</u>	NOT AUTHORIZED		
	For Licensing and Insurance details click here .		
<u>MC/MX/FF Number(s):</u>			
COMPANY INFORMATION			
<u>Legal Name:</u>	AFTERMATH HOT OIL SERVICES LLC		
<u>DBA Name:</u>			
<u>Physical Address:</u>	3514 W SUMRULD RD LOVINGTON, NM 88260-9826		
<u>Phone:</u>	(575) 200-8402		
<u>Mailing Address:</u>	3514 W SUMRULD RD LOVINGTON, NM 88260-9826		
<u>DUNS Number:</u>	--		
<u>Power Units:</u>	7	<u>Drivers:</u>	4
<u>Operation Classification:</u>			
<input checked="" type="checkbox"/> Auth. For Hire	Priv. Pass.(Non-business)	State Gov't	
Exempt For Hire	Migrant	Local Gov't	
Private(Property)	U.S. Mail	Indian Nation	
Priv. Pass. (Business)	Fed. Gov't		
<u>Carrier Operation:</u>			
Interstate	<input checked="" type="checkbox"/> Intrastate Only (HM)	Intrastate Only (Non-HM)	
<u>Cargo Carried:</u>			
General Freight	<input checked="" type="checkbox"/> Liquids/Gases	Chemicals	
Household Goods	Intermodal Cont.	Commodities Dry Bulk	
Metal: sheets, coils, rolls	Passengers	Refrigerated Food	
Motor Vehicles	Oilfield Equipment	Beverages	

Drive/Tow away	Livestock	Paper Products
Logs, Poles, Beams, Lumber	Grain, Feed, Hay	Utilities
Building Materials	Coal/Coke	Agricultural/Farm Supplies
Mobile Homes	Meat	Construction
Machinery, Large Objects	Garbage/Refuse	Water Well
Fresh Produce	US Mail	

[ID/Operations](#) | [Inspections/Crashes In US](#) | [Inspections/Crashes In Canada](#) | [Safety Rating](#)

US Inspection results for 24 months prior to: **04/15/2024**

Total Inspections: 1

Total IEP Inspections: 0

Note: Total inspections may be less than the sum of vehicle, driver, and hazmat inspections. Go to [Inspections Help](#) for further information.

Inspections:

Inspection Type	Vehicle	Driver	Hazmat	IEP
Inspections	0	1	0	0
Out of Service	0	0	0	0
Out of Service %	%	0%	%	0%
Nat'l Average % as of DATE 03/29/2024*	22.26%	6.67%	4.44%	N/A

*OOS rates calculated based on the most recent 24 months of inspection data per the latest monthly SAFER Snapshot.

Crashes reported to FMCSA by states for 24 months prior to: **04/15/2024**

Note: Crashes listed represent a motor carrier's involvement in reportable crashes, without any determination as to responsibility.

Crashes:

Type	Fatal	Injury	Tow	Total
Crashes	0	0	0	0

[ID/Operations](#) | [Inspections/Crashes In US](#) | [Inspections/Crashes In Canada](#) | [Safety Rating](#)

Canadian Inspection results for 24 months prior to: **04/15/2024**

Total inspections: 0

Note: Total inspections may be less than the sum of vehicle and driver inspections. Go to [Inspections Help](#) for further information.

Inspections:

Inspection Type	Vehicle	Driver
Inspections	0	0
Out of Service	0	0
Out of Service %	0%	0%

Crashes results for 24 months prior to: **04/15/2024**

Note: Crashes listed represent a motor carrier's involvement in reportable crashes, without any determination as to responsibility.

Crashes:

Type	Fatal	Injury	Tow	Total
Crashes	0	0	0	0

[ID/Operations](#) | [Inspections/Crashes In US](#) | [Inspections/Crashes In Canada](#) | [Safety Rating](#)

The Federal safety rating does not necessarily reflect the safety of the carrier when operating in intrastate commerce.

[Carrier Safety Rating:](#)

The rating below is current as of: **04/15/2024**

Review Information:

Rating Date:	None	Review Date:	None
Rating:	None	Type:	None

HOME

- Company Summary
- Cases List
- Company Rules
- Docs List
- DBA History
- Certification
- Authority
- Insurance Hist.
- Inspection Fees
- Fees
- Notes

Company Information

Industry Type	Industry Sub Type	Ownership Type
TRANSPORTATION	<u>GENERAL COMMODITIES/PROPERTY</u>	LLC
Certification Status	Current Address?	Master Name Currrent?
<u>CERTIFIED</u>	YES	<u>YES</u>
Company Name	AFTERMATH HOT OIL SERVICES, LLC	
Address (Street 1st Line) / Mailing	3514 W SUMRULD RD	
Street (2nd Line)		
City	State	Zip
LOVINGTON	NM	88260-0000
County	Phone #	Company Code
LEA	575-200-8402	
Equipment Storage Location		
3514 W Sumruld Rd, Lovington, NM 88260		
Records Location		
Station Points		

Owner Information

Owner Name	DOMINIC RAY LEYVA		
Address (Street 1st Line) / Physical	3514 W SUMRULD RD		
Street (2nd Line)			
City	State	Zip	
LOVINGTON	NM	88260-0000	
Phone #	Email		
575-200-8402	AFTERMATHHOTOIL@OUTLOOK.COM		

Agent / Attorney Information

Agent (Attorney) Name	Alma Cabello		
Agent (Attorney) Name (2nd)			
Address (Street 1st Line)	1006 W AVE F		
Street (2nd Line)			
City	State	Zip	
Lovington	NM	88260-0000	
Phone #	Email	Last Update	Updated By
575-631-7533	ALMATCABELLO@OUTLOOK.COM	02/07/2024	GARCIA, JUSTIN


Company's Current Case List (10 records)

Case #	Case Company Name (Address)	Case Type	File Date	Type	Case Status	Disposition
<u>24-00037-TRM</u>	<u>AFTERMATH HOT OIL SERVICES, LLC</u> (3514 W SUMRULD RD, LOVINGTON NM 88260-0000)	TRANSPORTATION	02/07/2024	PRIMARY	CLOSED	

Tips: Click Update button to update record or Delete button to delete record.

Copyright © CSI Technology Group. All rights reserved.

U.S. DOT# 3598466 has no current for-hire operating authority with FMCSA.



Learn About the CSA Prioritization Preview

FMCSA is proposing a new prioritization methodology to keep enforcement efforts focused on the carriers in most need of intervention. Learn more about these changes and how they will improve highway safety.

[Visit the CSA Prioritization Preview](#)

AFTERMATH HOT OIL SERVICES LLC

U.S. DOT#: 3598466
Address: 3514 W SUMRULD RD
LOVINGTON, NM 88260-9826
Number of Vehicles: 7
Number of Drivers: 4
Number of Inspections: 1

Safety Rating & OOS Rates

(As of 04/15/2024 updated daily from [SAFER](#))

Not Rated

Out of Service Rates

Type	OOS %	National Avg %
Vehicle		21.4
Driver	0.0	6.0
Hazmat		4.5

Licensing and Insurance

(As of 04/15/2024 updated hourly from [L&I](#))

Active For-Hire Authority		
Type	Yes/No	MC#/MX#
Property	No	
Passenger	No	
Household Goods	No	
Broker	No	

BASIC Status (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICS)

[View CSA Prioritization Preview](#) →
Based on a 24-month record ending March 29, 2024

Unsafe Driving	Crash Indicator	Hours-of-Service Compliance	Vehicle Maintenance	Controlled Substances and Alcohol	Not Public Hazardous Materials Compliance	Driver Fitness

Select a BASIC icon above to get details, or view your [Complete SMS Profile](#).

Summary of Activities

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Most Recent Investigation:

Carrier Registration

Subject to General Threshold

Enforcement Cases

(Six years as of 04/15/2024 updated monthly from [FMCSA](#))

No penalties found

Total Inspections: 1

Total Inspections without

Violations used in SMS: 1

Total Inspections with

Violations used in SMS: 0

Total Crashes* : 0


*Crashes listed represent a motor carrier's involvement in [reportable crashes](#), regardless of the carrier's or driver's role in the crash. [Continue for details](#).


USE OF SMS DATA/INFORMATION

FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A  symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The  symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at <http://safer.fmcsa.dot.gov> and motor carrier licensing and insurance status are available at <http://li-public.fmcsa.dot.gov/>.

[HOME](#)

Search Information

[Home](#)

Entity Details

Business ID#: **6411738**Status: **Active**Entity Name: **Aftermath Hot Oil Services, LLC**Standing: **Good Standing**DBA Name: **Not Applicable**

Entity Type and State of Domicile

Entity Type: **Domestic Limited Liability Company**State of Incorporation: **New Mexico**Statute Law Code: **53-19-1 to 53-19-74**

Formation Dates



Reporting Information



Period of Existence and Purpose and Character of Affairs



Outstanding Items

Not Applicable

Registered Agent:

No Records Found.

License:

No Records Found.

Contact Information

Mailing Address: **3514 W Sumruld Rd, Lovington, NM 88260**Principal Place of Business
Anywhere: **3514 W Sumruld Rd, Lovington, NM 88260**Secondary Principal Place of
Business Anywhere:Principal Office Outside of New
Mexico: **Not Applicable**Registered Office in State of
Incorporation:

Principal Place of Business in
Domestic State/ Country: **Not Applicable**

Principal Office Location in NM: **Not Applicable**

Registered Agent Information

Name: **Dominic Ray Leyva**

Geographical Location
Address:

Physical Address: **3514 W Sumruld Rd,
Lovington, NM 88260**

Mailing Address: **3514 W Sumruld Rd,
Lovington, NM 88260**

Date of Appointment: **03/25/2021**

Effective Date of Resignation:

Director Information

Not Applicable

Officer Information

Not Applicable

Manager Information

No Records to View.

Member Information

Title	Name	Address
Member	Dominic Ray Leyva	3514 W Sumruld Rd, Lovington, NM 88260

Organizer Information

Title	Name	Address
Organizer	Dominic Ray Leyva	3514 W Sumruld Rd, Lovington, NM 88260

Incorporator Information

Not Applicable

Trustee Information

Not Applicable

Filing History



License History



[Back](#)

[Entity Name History](#)

[Return to Search](#)