District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

Release Notification and Corrective Action

nMLB1125249455						OPERATOR			In	ıtial Report	Final Report
Name of Company Oxy Permian LTD. 16696						Contact Dusty Wilson					
Address 1017 W. Stanolind Rd						Telephone No. (575) 397-8247					
Facility Name Federal 29 # 8 Battery						Facility Type Production					
Surface Owner BLM Mineral Owner						BLM Lease No. 30-015-27266					
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West L	ine	County	
M	29	23s	31e							Eddy	
LatitudeLongitude											
NATURE OF RELEASE											
Type of Relea	ase				Volume of Release Volume 60 bbls 20 bbls				Recovered		
Source of Release						Date and F	e Date	Date and Hour of Discovery			
Hole in tank						07/30/2011 07/30/2011				1	
Was Immediate Notice Given? XX Yes ☐ No Not Required						If YES, To Whom? Mike Bratcher(NMOCD) Terry Gregston (BLM) via email					
By Whom? CJ Summers						Date and Hour 07/31/2011					
Was a Watercourse Reached? Yes X No						Date and Hour 07/31/2011 If YES, Volume Impacting the Watercourse. n/a approximately 60 bbls of oil covering a area approximately 50' x 50'. A Vac					
If a Watercourse was Impacted, Describe Fully.*											
N/A ANG A ARTES											
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \											
Describe Cause of Problem and Remedial Action Taken.*											
Hole developed in bottom area of tank due to corrosion and spilled out approximately 60 bbls of oil covering a area approximately 50' x 50'. A Vac Truck was dispatched to the area and recovered 20 bbls of free standing fluids. Remediation efforts continue. Will remediate to NMOCD guidelines.											
Describe Area Affected and Cleanup Action Taken.*											
Remediate to NMOCD Guidelines											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
							OIL CON	SERVATI	ON	DIVISION	1000
Signature: (MA)						Signed By Mile Benning					
Printed Name. Dusty L Wilson						Approved by District Supervisor:					
Title: HES Specialist						Approval SEP 0 9 2011					
E-mail Addre	ess. dusty_	wilson@oxv.	com			Conditions o					,
Date: 08/24/			none. (575) 397-8		Remediation per OCD Rule Guidelines. SUBMIT REMEDIA PROPOSAL NOT LATER THAN				Attached		
		nal Sheets If							2RP	-884	

Bratcher, Mike, EMNRD

From: Dusty_Wilson@oxy.com

Sent: Sunday, July 31, 2011 1:43 PM

To: Bratcher, Mike, EMNRD; Terry_Gregston@blm.gov

Cc: Chancey_Summers@oxy.com

Subject: Immediate notice of Reportable leak at the Oxy, Federal 29 # 8 Battery

Mike and Terry, this is to inform you of a Reportable leak that Oxy had 7/30/11 at the Federal 29 # 8 Battery, Sec 29 T23S R31E Eddy County. The leak was reported as being from hole developed in the bottom of the oil storage tank. We have lost 60 bbls of oil, and recovered 20 bbls of oil via Vac Truck. The leak was contained within the 50' X 50' firewalls at the battery. This site is located down State Rd 128 at MM 14 turn south on Pure Gold Rd. go south across 2nd cattle guard to 2nd rd. Turn right and go to battery. A Initial C-141 will be forth coming. Thanks

Thanks,

Dusty L. Wilson HES Specialist Seminole, Lea County RMT.

"You will never succeed, if not given the chance to fail."

Bratcher, Mike, EMNRD

From:

tareasto@blm.gov

Sent:

Sunday, July 31, 2011 6:28 PM

To:

Dusty_Wilson@oxy.com

Cc:

Chancey_Summers@oxy.com; Bratcher, Mike, EMNRD; Terry_Gregston@blm.gov

Subject: Re: Ir

Re: Immediate notice of Reportable leak at the Oxy, Federal 29 # 8 Battery

I have received your notification.

Thank you,

Terry Gregston Environmental Protection Specialist Bureau of Land Management 620 E. Greene St. Carlsbad, NM 88220 Office (575) 234-5958 Cell (575) 361-2635 Fax (575) 234-5927

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

< Dusty Wilson@oxy.com >

To <mike bratcher@state.nm.us>, <Terry Gregston@blm gov> cc <Chancey Summers@oxy com>

07/31/2011 01:43 PM

Subject Immediate notice of Reportable leak at the Oxy, Federal 29 # 8 Battery

Mike and Terry, this is to inform you of a Reportable leak that Oxy had 7/30/11 at the Federal 29 # 8 Battery, Sec 29 T23S R31E Eddy County. The leak was reported as being from hole developed in the bottom of the oil storage tank. We have lost 60 bbls of oil, and recovered 20 bbls of oil via Vac Truck. The leak was contained within the 50' X 50' firewalls at the battery. This site is located down State Rd 128 at MM 14 turn south on Pure Gold Rd. go south across 2nd cattle guard to 2nd rd. Turn right and go to battery. A Initial C-141 will be forth coming. Thanks

Thanks,

Dusty L. Wilson HES Specialist Seminole, Lea County RMT.

"You will never succeed, if not given the chance to fail."