

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 1 2011

Form C-141
Revised October 10, 2003

Submit Copy to appropriate District Office in accordance with 19 15 29 NMAC
NMOCD ARTESIA

Release Notification and Corrective Action

nMLB1130855162		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Linn Operating		269324	Contact Joe Hernandez		
Address 2130 W. Bender Hobbs, NM 88240		Telephone No 575-738-1739			
Facility Name: Fren Oil # 23		Facility Type Producing Oil Well			
Surface Owner BLM		Mineral Owner. BLM		API No. 3001528822	

LOCATION OF RELEASE

Unit Letter O	Section 19	Township 17S	Range 31E	Feet from the 10	North/South Line S	Feet from the 1475	East/West Line E	County EDDY
------------------	---------------	-----------------	--------------	---------------------	-----------------------	-----------------------	---------------------	----------------

Latitude: 32° 48' 46.6" Longitude: -103° 54' 19.1"

NATURE OF RELEASE

Type of Release, Land <i>Oil & Produced Water</i>	Volume of Release 4-6	Volume Recovered 3-5
Source of Release: Oil - Water <i>Stuffing box</i>	Date and Hour of Occurrence 10/27/2011 10 30am	Date and Hour of Discovery 10/27/2011 11 00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M Bratcher-NM OCD	
By Whom? Joe Hernandez	Date and Hour 10/27/2011 11 00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully *		
Describe Cause of Problem and Remedial Action Taken * Stuffing box blew out		
Describe Area Affected and Cleanup Action Taken * Called out vac truck and picked up all fluids		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations		
Signature <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name Joe Hernandez	Signed By <i>[Signature]</i> Approved by District Supervisor	
Title Production Foreman	Approval Date NOV 04 2011	Expiration Date
E-mail Address jhernandez@linenergy.com	Conditions of Approval Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <i>12/4/2011</i>	Attached <input type="checkbox"/>
Date 11/01/2011	Phone 575-942-9492	

* Attach Additional Sheets If Necessary

2RP-944

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Tuesday, November 01, 2011 2:05 PM
To: Terry Gregston (tgregsto@blm.gov); Bratcher, Mike, EMNRD
Cc: Daniel Frick; Joe Hernandez
Subject: Linn Energy - Fren # 23- Initial C141
Attachments: Fren Oil #23 Initial C141 11-01-11.pdf

To Mike & Terry;

Please find attached the C141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com