

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1000 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
NOV 15 2011
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB1031240514 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	F.U.N. State #1H	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-37879
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	30	26S	28E	800	North	330	East	Eddy

Latitude 32 01.143 Longitude 104 07.132

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	20bbls
Source of Release	Water tank	Date and Hour of Occurrence	10/26/2010	Date and Hour of Discovery	10/26/2010 6:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The natural gas water pump did not start, causing the water tank to overflow. Had mechanic check pump. Removed valve handle on supply gas valve to prevent accidental adjustment.

Describe Area Affected and Cleanup Action Taken.*

Initially 20bbls was released from the water tank and we were able to recover all 20bbls with a vacuum truck. All fluid was contained inside the facility firewall which is lined with a 40mil plastic liner. The contaminated gravel has been removed and clean gravel has been added as necessary. The location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by	Signed By <i>M. L. Brennan</i> District Supervisor
Title:	HSE Coordinator	Approval Date	NOV 15 2011 Expiration Date: N/A
E-mail Address:	jrusso@conchoresources.com	Conditions of Approval:	N/A <i>Final</i> Attached <input type="checkbox"/>
Date:	11/14/2011 Phone:	432-212-2399	

Attach Additional Sheets If Necessary

2RP-465

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Monday, November 14, 2011 2:32 PM
To: Bratcher, Mike, EMNRD
Subject: C-141 Final Report - F.U.N. State #1H TB
Attachments: img-Y14162945-0001.pdf

Mr. Bratcher,

Please see attached the C-141 Final report for a release that occurred last year on 10/26/2010. According to my records a Final Report had not yet been submitted for this spill. I wanted to be sure you had one for your files.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.