

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 10 2011

NMOCD ARTESIA

Submit 1 Copy to appropriate District Office in accordance with 19.15 29 NMAC

Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

MLB/131448507

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739
Facility Name: Federal F # 1		Facility Type: Producing Oil

Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001505655
--------------------	--------------------	---------------------

LOCATION OF RELEASE

Unit Letter A	Section 31	Township 18S	Range 31E	Feet from the 660	North/South Line N	Feet from the 660	East/West Line E	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude: Longitude:

NATURE OF RELEASE



Type of Release: Land Produced Water	Volume of Release: 75-130	Volume Recovered: 0
Source of Release: Produced Water Transport Unauthorized Dump	Date and Hour of Occurrence: 11/2/2011 8:00am	Date and Hour of Discovery: 11/2/2011 8:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD ; Terry Gregston- NM BLM	
By Whom? Joe Hernandez	Date and Hour 11/3/11 10:58am ; 12:44pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Transport pulled onto location during night and dumped load of PW on pad

Describe Area Affected and Cleanup Action Taken.* : Will pick up soil and remove.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Approved by: Signed By: 	
Title: Production Foreman	NOV 10 2011	Approval Date: Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/09/11 Phone: 575-942-9492	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

12/10/2011

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Thursday, November 10, 2011 11:18 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Federal F #1 C141 Initial 11-9-11
Attachments: Federal F # 1 C141 Initial 11-10-11.pdf

Please find attached the Initial C141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com