

District I
1625 N French Dr, Hobbs, NM 88240
District II
811 S First St, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company <i>B.C. Operating</i>	Contact <i>Jerry Livingston</i>
Address	Telephone No. <i>432 664 3189</i>
Facility Name <i>Wills Federal # 14</i>	Facility Type <i>Battery</i>

Surface Owner	Mineral Owner	API No. <i>30-025-33561-00-00</i>
---------------	---------------	-----------------------------------

LOCATION OF RELEASE *30-025-33561-00-00*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>B</i>	<i>35</i>	<i>26S</i>	<i>37E</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>Lea</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Oil & produce water</i>	Volume of Release <i>198 BBL</i>	Volume Recovered <i>89 BBL</i>
Source of Release <i>210 BBL Oil Tank</i>	Date and Hour of Occurrence <i>11.18</i>	Date and Hour of Discovery <i>11.18 12:00pm</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>8:00am</i> <i>Sylvia - OCD</i>	
By Whom? <i>Jerry Livingston</i>	Date and Hour <i>11.18.2011</i>	<i>2:45pm</i>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>none</i>	

If a Watercourse was Impacted, Describe Fully *
none
GW @ 170'

Describe Cause of Problem and Remedial Action Taken.*
1" connection on back of tank failed causing fluid in tank to spill on east side of pad in pasture 180 x 30 - 89 BBL was recovered

Describe Area Affected and Cleanup Action Taken.*
Pasture area behind tanks on east side of pad - Area will be scraped up and hauled off for disposal. Area will then be sampled to determine what depth area must be taken down to.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Juan F. Abalos</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Juan F. Abalos</i>	Approved by Environmental Specialist: <i>Jeffrey Salinger</i>	
Title: <i>Pumper</i>	Approval Date: <i>11/22/11</i>	Expiration Date: <i>01/24/11</i>
E-mail Address: <i>juanabalos35@yahoo.com</i>	Conditions of Approval: <i>SUBMIT FINAL C-141 BY 01/24/11</i>	Attached <input type="checkbox"/>
Date: <i>11-22-11</i> Phone: <i>(505) 441-1733</i>		<i>REP-11-11-2765</i>

* Attach Additional Sheets If Necessary