

HOBBS OCD

## District I

1625 N French Dr, Hobbs, NM 88240

## District II

811 S First St, Artesia, NM 88210

## District III

1000 Rio Brazos Road, Aztec, NM 87410

## District IV

1220 S St Francis Dr., Santa Fe, NM 87505

JAN 10 2012

RECEIVED

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505Form C-141  
Revised August 8, 2011Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>B.C. Operating</i>	Contact <i>Jerry Livingston</i>
Address <i>P.O. Box 50820 Midland TX</i>	Telephone No. <i>432-664-3189</i>
Facility Name <i>Wills Federal #14</i>	Facility Type <i>Battery</i>
Surface Owner	Mineral Owner
API No. <i>30-025-33561</i>	

## LOCATION OF RELEASE

Unit Letter <i>B</i>	Section <i>35</i>	Township <i>26S</i>	Range <i>37E</i>	Feet from the	North/South Line	Feet from the	East/West Line	County <i>Lea County</i>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release <i>Oil</i>	Volume of Release <i>13.33</i>	Volume Recovered <i>0</i>
Source of Release <i>Oil tank Valve</i>	Date and Hour of Occurrence <i>12-28</i>	Date and Hour of Discovery <i>12-28</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>12:00</i>	
By Whom? <i>N/A</i>	Date and Hour <i>N/A</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>None</i>	

If a Watercourse was Impacted, Describe Fully.\*

*\* none**GW @ 170'*

Describe Cause of Problem and Remedial Action Taken.\*

*Valve coming off front of oil tank had handle on it, cow brushed up against handle opening valve causing 13.33 BBL of oil to flow onto ground and run behind tanks into initial clean up excavation was 3-4'*

Describe Area Affected and Cleanup Action Taken.\*

*Area affected was bottom of initial excavation at depth of 3-4' Had backhoe scrape oil and haul off for disposal initial sampling will be done on bottom of excavation.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: <i>Juan F. Abalos</i>	Approved by Environmental Specialist: <i>Jeffrey</i>	
Printed Name: <i>Jua F. Abalos</i>	Approval Date: <i>1/12/12</i>	Expiration Date: <i>3/12/12</i>
Title: <i>Pumper</i>	Conditions of Approval: <i>SUBMIT FINAL</i>	
E-mail Address: <i>juanabalos35@yahoo.com</i>	Date: <i>1-11-12</i> Phone: _____	Attached <input type="checkbox"/> <i>C-141 BY 3/12/12</i> <i>IRP-1-12-2776</i>

\* Attach Additional Sheets If Necessary

HOBBS OCD

RECEIVED

JAN 25 2012