<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Di , Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

FEB 28 2012

RECEIVED

Form C-141 Revised October 10, 2003

NMOODHARTES Are priate District Office in accordance with 19.15 29 NMAC

Oil Conservation Division 1220 South St. Francis Dr.

ZFUTSED

2RP-1054

	·			Sa	nia re	2, NM 8/3	US		_	(1~		
	··		Rele	ase Notific	ation	and Co	rrective A	ction				
NMLB1206131638						OPERATOR			☐ Initial Report ☐ Final Repo			Final Report
		inn Operatin	g	269324	- I	Contact: Joè	Hernandez					
		nder Hobbs.					lo.: 575-738-17	39				
						Facility Type: Oil Well						
Surface Owner: Federal Mineral Owner:						Federal			API No.: 3001526621			
						V OF DEI	FASE					
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County												
L	29	17S	31E	2590		South 100			Vest	County	Edd	у
Latitude: 32.8054229524098 Longitude: -103.900125487933  NATURE OF RELEASE												
Type of Rele	ase: Produc	ed Water/ Oil	Condensa		UILL				Volume Recovered: 2 / 10gal.			
Source of Re			001.00			<del></del>	our of Occurrence	e:		Hour of Discovery:		
Was Immedia	ate Notice (		Yes [	No Not Re	equired	If YES, To Whom?						
By Whom? J	oe Hernand	lez				Date and Hour 02/07/2012 3:00pm						
Was a Watercourse Reached?  ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.						
10 117		pacted, Descr				L						
Describe Cause of Problem and Remedial Action Taken.*: 2" Flow line pressured up and clamp gave out												
Describe Are Further remd			Action Tal	cen.* : leaking ou	t 151ft x	: 2ft wide on s	ide of lease road	and nex	t to unit TB	#99. A.C	.D. Va	c Truck.
regulations a public health should their or or the environ	Il operators or the envi operations l nment. In a	are required tronment. The nave failed to	o report an acceptand adequately OCD accep	e is true and comp nd/or file certain r ce of a C-141 repo v investigate and r otance of a C-141	elease nort by the emediat	otifications a e NMOCD m e contaminati	nd perform correct arked as "Final Ro on that pose a thre	tive act eport" c eat to g	ions for rele loes not relic round water	eases which eve the ope , surface w	may e rator o ater, hu	endanger of liability uman health
l	1.	and the same	and the same of		}		OIL CON:	SERV	ATION	DIVISION	<u>NC</u>	
4. The Second Se												
Printed Name: Joe Hernandez						Approved by District Supervisor: 1/4 Describer						
Title: Production Foreman						Approval Date: Expiration Date:						
E-mail Address: jhernandez@linnenergy.com						Conditions of Approval:  Attached						
Date: 2/28/29				5-942-9492				aules i	&			
Attach Additional Sheets If Necessary					_	Remediation per OCD Rules &						

Guidelines. SUBMIT REMEDIATION

PROPOSAL NOT LATER THAN:

## Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]

Sent: Tuesday, February 28, 2012 1:37 PM

To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)

Cc: Daniel Frick; Ron Ragland

Subject: Linn- Turner B #99 Initial C-141 2/7/12 Attachments: Turner B #99 Initial C-141 2-7-12.pdf

Please find attached the revised Initial C-141 for the above referenced location.

Thank you,

Theresa McCracken LINN Operating 2130 W. Bender Blvd Hobbs, NM 88240 (575)738-1739 tmccracken@linnenergy.com

## Bratcher, Mike, EMNRD

From: Sent:

Joe Hernandez [JHernandez@linnenergy.com]

To:

Wednesday, February 08, 2012 6:30 PM Terry Gregston; Bratcher, Mike, EMNRD Turner B South #99

Subject:

Terry Mike,

We had a flow line pressure up and blow a clam and release product on the pad and beside lease road Monday afternoon. C-141 will be turned in asap.

Thanks Joe

Turner B south #99

Unit L Sec.29-T17S-R31E, 2590 'FSL 100' FEL Eddy County NM LC-029395B

P.S. I am unable to e-mail Jerry Blakely could I bother you for his e-mail.

OP sent Revised Copy

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. Francis Dr. Santa Fe. NM 87505

State of New Mexico
Energy Minerals and Natural Resources

FEB 28 2012

Form C-141 Revised October 10, 2003

NMOCD ARTOF SHAPP opriate District Office in accordance with 19.15.29 NMAC

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

220 S. St. Francis Dr., Santa Fe, NM 87505 San						, NM 875	05					
	-	,	Rele	ase Notific	ation	and Co	rrective A	ction				
						<b>OPERA</b>	TOR .		🛚 Initia	al Report	Final Report	
Name of Co	mpany: Li	nn Operatin			Contact: Joe Hernandez							
Address: 21	30 W. Ben	der Hobbs	240		Telephone No.: 575-738-1739							
Facility Nan	ne: Turner	B #99			Facility Type: Oil Well							
Surface Own	ner: Feder	al	Mineral C	wner: I	Federal			API No.: 3001526621				
				LOCA	TION	OF REI	LEASE					
Unit Letter L	Section 29	Township 17S	Range 31E	Feet from the 2590		South Line	Feet from the 100	the East/West Line Con West		County	Eddy	
			Latitu	ide: 32.8054229	9524098	8 Longitud	<b>e:</b> -103.900125	487933				
				NAT	URE	OF RELI	EASE					
Type of Release: Produced Water Volume of Release: 5								Volume Recovered: 2				
Source of Release: Polly Pipeline						Date and Hour of Occurrence: 02/07/2012 1:00pm			Date and Hour of Discovery: 02/07/2012 1:30pm			

NATURE OF RELEASE									
Type of Release: Produced Water	Volume of Release: 5	Volume Re	covered: 2						
Source of Release: Polly Pipeline	Date and Hour of Occurrence:		our of Discovery:						
	02/07/2012 1:00pm	02/07/2012	1:30pm						
Was Immediate Notice Given?	If YES, To Whom?								
☐ Yes ☐ No ☐ Not Required	M. Bratcher-NM OCD Terry Gre	egston-BLM							
By Whom? Joe Hemandez	Date and Hour 02/07/2012 3:00pm								
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.								
☐ Yes ⊠ No									
If a Watercourse was Impacted, Describe Fully.*:									
in a watercourse was impacted, Describe runy.									
			•						
Describe Cause of Problem and Remedial Action Taken.*: 2" Flow line p	pressured up and clamp gave out								
	1 10								
Describe Area Affected and Cleanup Action Taken.*: leaking out 151ft	x 2ft wide on side of lease road and no	ext to unit TB #	#99. A.C.D. Vac Truck.						
Further remdedial action pending.									
I hereby certify that the information given above is true and complete to	the hest of my knowledge and underst	and that nursu	ant to NMOCD rules and						
regulations all operators are required to report and/or file certain release	notifications and perform corrective ac	ctions for relea	uses which may endanger						
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability									
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health									
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other									
federal, state, or local laws and/or regulations.									
· 1. of may?	OIL CONSERVATION DIVISION								
Signature:									
Division In House In	Approved by District Supervisor:								
Printed Name: ,Joe Hernandez									
Title: Droduction Foreman	A	Paradara in D							
Title: Production Foreman	Approval Date:	Expiration Date:							
E mail Address ihamandas@linnanana.	Candidiana of Ammount		Augabad [7]						
E-mail Address: jhernandez@linnenergy.com  Date: 2/28/2012 Phone: 575-942-9492	Conditions of Approval:		Attached						
Date: 2/26/2012 Prione: 5/5-942-9492									

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

From:

Theresa McCracken [TMcCracken@linnenergy.com]

Sent:

To:

Tuesday, February 28, 2012 10:00 AM
Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Daniel Frick; Ron Ragland

Cc: Subject: Linn-Turner B #99 Initial C-141

Attachments:

Turner B #99 Initial C-141.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,

Theresa McCracken LINN Operating 2130 W. Bender Blvd Hobbs, NM 88240 (575)738-1739 tmccracken@linnenergy.com