

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
811 S. First St, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Basic Energy Services	Contact: Colt Miller	
Address: 2404 Texas Ave Eunice NM	Telephone No. 575-631-2093	
Facility Name: Lea FED SWD	Facility Type: Salt Water Disposal	
Surface Owner: PRIVATE	Mineral Owner: FEDERAL	API No. 30-025-27400

**LOCATION OF RELEASE**

Unit Letter B	Section 17	Township 23 South	Range 37 East	Feet from the 660	North/South Line North Line	Feet from the 1650	East/West Line East Line	County: Lea
------------------	---------------	----------------------	------------------	----------------------	--------------------------------	-----------------------	-----------------------------	-------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 23 bbl	Volume Recovered: 20
Source of Release: Gun Barrel	Date and Hour of Occurrence 4-30-12 @ 5pm	Date and Hour of Discovery 4-30-12 @ 5pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MARK WHITAKER	
By Whom? COLT MILLER	Date and Hour 05/03/12 10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Gun barrel was over filled. Phoenix Environmental is taking care of all remedial services. MAJORITY STAYED IN DIKE.

Describe Area Affected and Cleanup Action Taken.\*

North side of the Lea FED disposal had overspray on the surface. Phoenix Environmental is taking care of cleanup process

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Colt Miller	Approved by Environmental Specialist: 		
Title: Area Superintendent	Approval Date: 5/03/12	Expiration Date: 7/03/12	
E-mail Address: Colt.Miller@basicenergyservices.com	Conditions of Approval: SUBMIT FINAL C-141 BY 07/03/12		Attached <input type="checkbox"/>
Date: 5-3-12	Phone: 575-631-2093	IRP-5-12-2805	

\* Attach Additional Sheets If Necessary