


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB 12109 41467

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC <i>229/37</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	White Oak State #1	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-29749
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter P	Section 23	Township 17S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.8150 Longitude 104.1392

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 20bbls	Volume Recovered 18bbls
Source of Release Water tank	Date and Hour of Occurrence 03/25/2012	Date and Hour of Discovery 03/25/2012 4:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Water tank ran over due to loss of power at the facility. CVE returned power.

Describe Area Affected and Cleanup Action Taken.*

Initially 20bbls were released from the water tank and we were able to recover 18bbls with a vacuum truck. The fluids released inside the dike area and measured an area of roughly 5' x 30'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will submit a work plan for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Signed By 	
Printed Name: Josh Russo	Approved by District Supervisor:	
Title: HSE Coordinator	Approval Date: APR 18 2012	Expiration Date:
E-mail Address: jrusso@conchoresources.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 04/05/2012 Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

2 RP-1096

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Thursday, April 05, 2012 1:57 PM
To: Bratcher, Mike, EMNRD
Subject: C-141 Initial Report
Attachments: WHITE OAK STATE TANK BATTERY -- DATE OF INITIAL -- 03-28-2012.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 03/28/2012.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.