District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

APR 2.6 2012

RECEIVED

Form C-141 Revised October 10, 2003

NMO COMMITTE Shardpriate District Office in with 19.15.29 NMAC

Oil Conservation Division Santa Fe, NM 87505

1220 South St. Francis Dr.

Release Notification and Corrective Action OPERATOR Initial Report Final Report nMLB/214437340 Name of Company: Linn Operating Contact: Joe Hernandez Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739 Facility Name: CA Russell #15 Facility Type: Oil API No.+-300158757 Surface Owner: Federal Mineral Owner: Federal 30-015-28757 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County F 18 17S 31E 1500 1950 Eddy Norh West Latitude: 32.8376298363716 Longitude: -103.910552975336 NATURE OF RELEASE Type of Release: Oil / Produced Water Volume of Release: 4 / 2 Volume Recovered: 3 / 1 Date and Hour of Occurrence: Date and Hour of Discovery: Source of Release: Poly-pipeline 04/16/2012 1:30pm 04/16/2012 1pm Was Immediate Notice Given? If YES, To Whom? Terry Gregston-BLM By Whom? Joe Hemandez Date and Hour 04/17/2012 1pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.*: Describe Cause of Problem and Remedial Action Taken.*: Roustabout crew was walking lines and spot a clamp leaking on existing unknown contaminated area, crew removed clamp and fuse line back together, and used vac truck to recover fluid Describe Area Affected and Cleanup Action Taken.*: Further remedial action pending... I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Signed By Approved by District Supervisor Printed Name: Joe Hernandez Approval MAY 2 3 2012 Title: Production Foreman **Expiration Date:** E-mail Address: jhernandez@linnenergy.com Conditions of Approval: Attached Remediation per OCD Rules & Date: 04/26/2012 Phone: 575-942-9492

* Attach Additional Sheets If Necessary

Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 23/20/2

2RP-1125

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]

Sent: Thursday, April 26, 2012 9:36 AM

To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)

Cc:Daniel Frick; Ron RaglandSubject:Linn- CA Russell #15 Initial C-141Attachments:CA Russell #15 4-16-12 .pdf

Please find attached the Initial C-141 for the above referenced location.

Thank you,

Theresa McCracken LINN Operating 2130 W. Bender Blvd Hobbs, NM 88240 (575)738-1739 tmccracken@linnenergy.com