District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in

Form C-141

Revised August 8, 2011

			Rel	ease Notific	cation and Co	orrective A	ction			
MLBI	15034	852			OPERA'	TOR	🔯 Initi	al Report		Final Report
Name of Company Apache Corporation 873					Contact Na	Contact Natalie Gladden				
Address PO Box 1849, Eunice NM 88231						Telephone No. 575-390-4186				
Facility Nat	ne Loco l	Federal Batte	ery (Loco	Federal #1)	Facility Typ	Facility Type Production Facility				
Surface Owner Unknown				Mineral (Mineral Owner BLM			API No. 30-015-30144		
				LOCA	ATION OF RE	LEASE				
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County		
В	21	17S	30E	990'	FNL	2310	FEL	Eddy		

Latitude Longitude **NATURE OF RELEASE** Volume of Release 10 Type of Release Hydrocarbons Volume Recovered 9 Source of Release "T" Connector Date and Hour of Occurrence Date and Hour of Discovery 12/6/11 12/6/11 Was Immediate Notice Given? If YES, To Whom? Yes No Not Required Mike Bratcher By Whom? Natalie Gladden Date and Hour 12/07/11 1153am Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes 🛛 No RECEIVED If a Watercourse was Impacted, Describe Fully.* APR 3 0 2012 NMOCD ARTESIA Describe Cause of Problem and Remedial Action Taken.* The "T" connector to the header from the circulating pump broke. Describe Area Affected and Cleanup Action Taken.* Contamination will be hand dug and will meet the NMOCD Guidelines to closure. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Approved by Environmental Special Printed Name: Natalie Gladden Approval Dat MAY 29 2012 Title: EHS Environmental Tech Expiration Date: E-mail Address: natalie.gladden@apachecorp.com Conditions of Approval: Attached | Remediation per OCD Rules & Phone: 575-390-4186

* Attach Additional Sheets If Necessary

LATE SUBMITTER

Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 6/29/00/2

2RA-1/31

Bratcher, Mike, EMNRD

From: Gladden, Natalie [Natalie.Gladden@apachecorp.com]

Sent: Wednesday, December 07, 2011 10:53 AM

To: Bratcher, Mike, EMNRD; Amos, James A (jamos@blm.gov)

Subject: Loco Federal Battery

Importance: High

Yesterday at the Loco Federal Battery, the "T" connection to the header from the circulating pump broke and released 10bbls of oil and we recovered 9bbls.

Nearest well: Loco Federal #1

30-015-30144 B-21-17S-30E 990FNL and 2310FEL

I will be sending the C141 and spill notification shortly.

Thanks and have a great day!

Natalie Gladden

Apache Corporation EHS Environmental Tech New Mexico District Cell: 575-390-4186

Office: 575-394-1503 x 1258

Fax: 575-394-2425

Email: natalie.gladden@apachecorp.com