


District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB1223742023

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Plains Pipeline, LP <u>34053</u>	Contact	Jason Henry
Address	2530 Hwy 214 -- Denver City, Tx 79323	Telephone No.	(575) 441-1099
Facility Name	Taylor Poly 4-inch	Facility Type	Pipeline

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	34	23S	31E					Eddy

Latitude N 32.26083° Longitude W 103.75771°

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	37 bbls	Volume Recovered	35 bbls
Source of Release	4-inch poly pipeline was damaged by excavator	Date and Hour of Occurrence	07/14/2012 @ 1400	Date and Hour of Discovery	07/14/2012 @ 1400
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Verbal notification to Mike Bratcher on 07/17/2012		
By Whom?	Jason Henry	Date and Hour	07/17/2012 @ 1430		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4-inch poly pipeline was struck by the bucket of an excavator. The free product was recovered with a vacuum truck.

Describe Area Affected and Cleanup Action Taken *

The released crude pooled in the ditch line of new pipeline that was being installed. The impacted area will be remediated per applicable BLM/NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Jason Henry</u>	Signed By <u>M. Bratcher</u>	
Printed Name: Jason Henry	Approved by District Supervisor:	
Title: Remediation Coordinator	Approval Date: AUG 24 2012	Expiration Date:
E-mail Address: jhenry@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>07/18/2012</u> Phone: (575) 441-1099	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 9/24/2012	

* Attach Additional Sheets If Necessary

NMLB1223741020

NMLB1223742420

NMLB1223742556 (Compliance mod)

NMLB1223742652

2 RA-1259