

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCT 24 2012

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU 0546-002	Facility Type Oil and Gas

Surface Owner State Of New Mexico	Mineral Owner State Of New Mexico	Lease No 300252693200
-----------------------------------	-----------------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter G	Section 5	Township 18S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N 32 46.671 Longitude W 103 28.596

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 17bbl (0oil, 17water)	Volume Recovered (0oil, 0water)
Source of Release 1 inch well head steel injection line	Date and Hour of Occurrence 10/23/12 ~0430	Date and Hour of Discovery 10/23/12 0900
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Hole in a 1 inch steel buried injection line due to suspected corrosion. Well was shut in and water turned off. Vacuum truck was called but by the time the truck arrived all fluids had soaked into the ground.

Describe Area Affected and Cleanup Action Taken.*

The affected area is a 400' X 45' X 1" area of caliche well pad and grassy pasture land. No fluids could be recovered. The spill site will be delineated/remediated in accordance with an agreement with NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by District Supervisor:  Environmental Specialist	
Title: HSER Lead	Approval Date: 10/26/12	Expiration Date: 12/26/12
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 10/24/12 Phone: 505.391.3158	C-141 BY 12/26/12	IRP-10-12-2859

• Attach Additional Sheets If Necessary