1625 N. French Dr., Hobbs, NM 88240 Energy Miner District II Energy Miner 1301 W. Grand Avenue, Artesia, NM 88210 Oil Cor District III 001 Cor 1000 Rio Brazos Road, Aztec, NM 87410 1220 Sc District IV 1220 Sc 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa						of New Mexico als and Natural Resources servation Division uth St. Francis Dr. Fe, NM 87505 ion and Corrective A OPERATOR Contact Christopher Jon Telephone No. (575) 62 Facility Type Productio			Initial Report Final Report nes 28-4121				
		T				N OF REI							
Unit Letter	Section 35	Township 2/5	Range 23 E	_		South Line	Feet from the	}	West Line	County	y J		
	4	188-	33E-	1500		5 2080			E	Eddy County, NM			
Latitude <u>N 32.43196°</u> Longitude <u>W 104.57110°</u>													
NATURE OF RELEASE													
Type of Relea		uced water				Volume of				Recovered 0 bbls			
Source of Rei	lease Fai	lure in 3" poly	y productio	on line		Date and H 9/21/2012	lour of Occurrenc @ 8:00 am	nce Date and Hour of			covery		
Was Immedia	te Notice (If YES, To Whom?							
		X	Yes L	No 🗌 Not Re	equired	Mike Bratcher- NMOCD, Terry Gregston-BLM							
By Whom?						Date and Hour 09/21/2012 @ 9:10 am							
Was a Watero	course Read		Yes 🛛	No		If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Γully.* Describe Cause of Problem and Remedial Action Taken.* The failure of a 3" poly production line caused 20 bbls of produced water to leak onto the ground. 0 bbls were recovered and the line was repaired.													
Describe Area Affected and Cleanup Action Taken.* The area affected was approximately 60' x 60'. Remediation will be performed according to an OCD and BLM approved remediation plan. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to acceptance water, human health													
or the environ federal, state,				tance of a C-141	report do	bes not reliev	e the operator of r	espons	ibility for co	ompliance w	ith any	other	
Jouorai, State,	or rocar per					OIL CONSERVATION DIVISION							
Signature.							Annual hu District Summing All Kanna						
Printed Name: Christopher Jones A							Approved by District Superviserigned By M1/4 Bannul						
Title: HES Specialist A							Approval Date:						
E-mail Addre	E-mail Address: Christopher Jones@oxy.com						Conditions of Approval: Attached						
	5/2012		Phor	ie: (575) 628-4	121								
* Attach Addit	ional Shee	ets If Necessa	ary		Guic Guic	lelines. SU POSAL NO	on per OCD R BMIT REMED DT LATER THA 2012	IATIC		2RP-	- 13:	20	

Bratcher, Mike, EMNRD

From:	Kathy Purvis <kathy@bbcinternational.com></kathy@bbcinternational.com>
Sent:	Wednesday, September 26, 2012 11:10 AM
То:	Bratcher, Mike, EMNRD; jamos@blm.gov
Cc:	christopher_jones@oxy.com;
	kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject:	Initial C-141 for Federal C 35 #003
Attachments:	Initial C-141, signed 9-25-12 and sent 9-26-12.pdf

Attached is the initial C-141 for a leak occurring in Eddy County, NM at the Federal C 35 #003. Receipt notification response via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388 Fax: (575) 397-0397 Email: <u>kathy@bbcinternational.com</u>