

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised October 10, 2003

OCT 24 2012 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Southern Union Gas Services	Contact	Curt Stanley
Address	801 S. Loop 464, Monahans, TX 79756	Telephone No.	575-390-7595
Facility Name	Trunk D (10/15/12)	Facility Type	Natural Gas Pipeline
Surface Owner	State of New Mexico	Lease No.	30-025-38822

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	3	23S	36E					Lea

Latitude 32 degrees 20.130' North Longitude 103 degrees 14.997 West

NATURE OF RELEASE

Type of Release	Natural Gas, Crude Oil and Produced Water	Volume of Release	2 bbls liquid and 1,824 MCF gas	Volume Recovered	None
Source of Release	16 Inch Natural Gas Pipeline	Date and Hour of Occurrence	October 15, 2012 - 1030 hours	Date and Hour of Discovery	October 15, 2012 - 0900 hours
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A sixteen (16)-inch low pressure natural gas pipeline developed a leak, resulting in a release of natural gas, crude oil and produced water. During initial response activities the pipeline was shut-in to mitigate the release. Following initial response activities, the affected pipeline segment was replaced with 200 linear feet of 16 inch polypipe.

Describe Area Affected and Cleanup Action Taken *

The affected area is approximately 1,500 square feet. The release will be remediated according to NMOCD regulatory guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	 Environmental Specialist	
Printed Name: Curt D. Stanley	Approved by Environmental Specialist:	
Title: Environmental Specialist	Approval Date: 10/24/12	Expiration Date: 12/24/12
E-mail Address: curt.stanley@sug.com	Conditions of Approval: SUBMIT FINAL C-141 BY 12/24/12	Attached <input type="checkbox"/>
Date: October 15, 2012 Phone: 575-390-7595	IRP-10-12-2855	

* Attach Additional Sheets If Necessary