

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OCT 29 2012

State of New Mexico
Energy Minerals and Natural Resources

2102 6 2 100

Form C-141
Revised August 8, 2011

RECEIVED

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Key Energy Services	Contact Bob Fisher
Address Box 99 Eunice N.M.	Telephone No. 0-575-394-2581, C 575-631-7431
Facility Name Merit Energy Silver Oak Tank Bty	Facility Type Tank Battery
Surface Owner Tim Carlin	Mineral Owner State of New Mexico
API No: 30-025-38642	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
B	n-6	19s	35E	660	North	1980	East	

Latitude 32.69515 Longitude -103.49458

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20 bbls	Volume Recovered 15 bbls
Source of Release Transport Truck	Date and Hour of Occurrence 9:30 AM 10-6-2012	Date and Hour of Discovery Same
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Key Energy Service Supervisor Randy Corbell who informed Bob Fisher who is the District Manager	
By Whom? Randy Corbell	Date and Hour 10-6-2012 @ 9:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.*

JRL 06/04/13

GW @ 62'

Describe Cause of Problem and Remedial Action Taken.*

Transport truck left back valve open on trailer & pumped about 20 bbls of Produced Water on ground. He then proceeded to vacuum up 15 bbls of the spill. Contacted Chris Flores with Merit Energy who notified Mr Tim Carlin of the situation. Mr Carlin was out of town & would check it out on Monday when he returned. On Thursday, October 11th, Mr Carlin notified me that we needed to clean up an area that the water had ran down to. About 160' from the fence. At the present time we are waiting on a call to clear so we can excavate the area with a backhoe from RW1.

Describe Area Affected and Cleanup Action Taken.*

Some of the water escaped off the pad down the Southeast corner into the pasture for about 160'. We are waiting for a call to clear & OCD before proceeding with clean up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Robert Fisher	OIL CONSERVATION DIVISION	
Printed Name:	Approved by Environmental Specialist: <i>Jeffrey Sekins</i> Environmental Specialist	
Title: District Manager Key Energy Services yd 3008	Approval Date: 11/14/12	Expiration Date: 11/14/13
E-mail Address: rfisher@keyenergy.com	Conditions of Approval: FULLY DELINEATE	Attached <input type="checkbox"/> IRP-11-12-2869

HORIZONTALLY AND VERTICALLY.
IMMEDIATE TO NMOCD RRL,
SUBMIT FINAL C-141 BY 01/14/13

NOV 19 2012