


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMW 1231252031

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimarex Energy Company 215099	Contact Sheldon T. Waeger
Address 15 E. 5 th St, Suite 1000, Tulsa, OK 74103-4346	Telephone No. 918-557-4177
Facility Name Arkansas 23 Fee #3	Facility Type Production

Surface Owner	Mineral Owner	API No. 30-015-40192
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	23	195	25E	2310	N	990	E	Eddy

Latitude _N 32°38' 49.65" _ Longitude _W 104°27' 00.21" _

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 10 bbls.	Volume Recovered – 8-9
Source of Release – Flowback Frac Tank	Date and Hour of Occurrence - After 12:00 am on 10/25/2012	Date and Hour of Discovery – 1:00 am on 10/25/2012
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* During Completion/flowback operations a flowback frac tank was run over due to not being equalized with an adjacent tank. Approximately 10 bbls of produced flowback water was spilled out of the tank and onto the location. All fluids remained on location near the tank. A vacuum truck hauling off the flowback water was utilized and recovered approximately 8-9 bbls of water.

Describe Area Affected and Cleanup Action Taken.* The affected area was an approximate 15'-20' radius around the frac tank. A vacuum truck was on location and was utilized to suck up approximately 8-9 bbls of water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141-report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheldon T. Waeger	OIL CONSERVATION DIVISION	
Printed Name: Sheldon T. Waeger	Approved by Environmental Specialist: Signed By: <i>M. L. Brennan</i>	
Title: Superintendent, Environmental, Safety & Health	Approval Date: NOV 07 2012	Expiration Date:
E-mail Address: swaeger@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/02/2012 Phone: 918-557-4177		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION**

PROPOSAL NOT LATER THAN:

Dec. 7, 2012

2RP-1393

Bratcher, Mike, EMNRD

From: Terri Stathem <TStathem@cimarex.com>
Sent: Monday, November 05, 2012 6:04 AM
To: Bratcher, Mike, EMNRD
Cc: Sharp, Karen, EMNRD
Subject: C141 - Cimarex Energy
Attachments: 201211050703.pdf

Good morning. Please see attached C141 regarding a spill incident. I will also overnight mail the originals.

Thanks,

Terri Stathem
Coordinator - Regulatory Compliance
15 East 5th Street, Suite 1000
Tulsa, OK 74103-4346

Direct 918-295-1763 (Tulsa) 432-620-1936 (Midland)
Cell 918-633-9702
Fax 918-749-8059

Cimarex Energy Co.
15 East 5th Street
Suite 1000
Tulsa, Oklahoma 74103-4346
PHONE 918.585.1100
FAX 918.749.8059



November 2, 2012

Oil Conservation Division
District II
811 S. First Street
Artesia, New Mexico 88210

Re: Spill Notification and Corrective Action, Form C-141
Cimarex Energy Co.
Arkansas 23 Fee #3
Sec 23, 19S-25E, Eddy Co, NM

Dear Sir or Madam:

Enclosed are Spill Notification and Corrective Action Forms C-141 for two separate spill incidents that occurred on the Cimarex Energy Co., Arkansas 23 Fee #3, Sec 23, 19S-25E, Eddy Co, NM on October 25 & October 28, 2012.

I can be contacted at 918-557-4177 if there are any questions.

Sincerely,

A handwritten signature in cursive script that reads "Sheldon T. Waeger".

Sheldon T. Waeger
Cimarex Energy Co.
Superintendent, Environmental, Safety & Health