District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

### State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

## Release Notification and Corrective Action

MMIN	3205	52348							Final Report			
Name of Company: Devon Energy 6137						Contact: Roy White						
Address: 6488 Seven Rivers Highway, Artesia, N.M. 88210					Telephone No. 575-513-1741  Facility Type: Oil Well/API # 30-015-37220							
Facility Nar	ne: Dicker	is 29 Fed 3H				racility lyp	e: Oil Well/API	# 30-0	115-3/220	) 		
Surface Ow	ner			Mineral C	wner				Lease N	No. NMNM	I-5485	6
				LOCA	TION	OF RE	LEASE				•	
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/\	West Line	County		
Н	29	16S	28E	2310'	North		330'	East		Eddy		
	NATURE OF RELEASE											
Type of Rele	ase: produc	ed water spill		NAI	UKE	·	Release: 285 bbls	s	Volume I	Recovered: 2	85 bbls	
Source of Re			from tank			<del></del>	lour of Occurrenc			Hour of Disc		
						11/6/2012,			11/6/2012	2, 6PM		
Was Immedia	ite Notice (		Yes [	No Not Re	equired	If YES, To Brooke Ov	Whom? vens, Lease Opera	itor				
By Whom? I	Basic Energ	y Services				Date and I-	lour: 11/6/2012, 0	6:15PM				
Was a Water	course Reac					If YES, Vo	olume Impacting t	he Wate	ercourse.			
						<u> </u>				REC	<u> </u>	VED
If a Watercou	rse was Im	pacted, Descr	ibe Fully.	•					٠	NOV	14	2012
										NMOC	D AE	RTESIA
D. 7. C.	CD -1.1	, 1 D	11-1 A -41-	T-1 *						1111100		ITESIA
Describe Cau					n to a lo	ad line when	he hit it and caus	ed it to	senarate fro	om the tank	285 bb	ls of
				with 285 bbls rec		da iiic wiicii	no me n una caas	cu ii io	separate in	om the tank.	200 00	15 01
Describe Are									1:			
The 285 bbl s	spill occurre	at the Dicke	ens 29 Fed	13H location. Vac	cuum tru	cks were call	ed to clean it up a	ind the	line was rep	paired to resu	me serv	/ice.
I hereby certi	fy that the i	nformation gi	ven ahove	is true and comp	lete to th	ne best of my	knowledge and u	ndersta	nd that nurs	suant to NM(	OCD ru	les and
regulations al	loperators	are required to	o report ar	nd/or file certain r	elease no	otifications a	nd perform correc	tive act	ions for rel	eases which	may end	danger
							arked as "Final Ro					
							on that pose a three the operator of the					
federal, state,												
						OIL CONSERVATION DIVISION						
Signature: Kolyo A C. Kace												
A					Approved by	District Supervise	or:	Signed By	11/4	R)KM	redese_	
Printed Name	: Rebecca	Raga					. 4 5 0040					
Title: Field Admin Tech					Approval Date: Expiration Date:		Date:					
E-mail Address: Rebecca.raga@dvn.com					Conditions of Approval:			_				
_						Conditions Of	. r.pprovar.			Attached		
	Date: 11/8/2012 Phone: 575-746-5564 Attach Additional Sheets If Necessary 7RP-1400-							MAC				
Attaon Audi	.ionai onec	11 1400033	uı y			Remed	iation per OCD	Rules	s &	ZΚ	1-/	400
					C	Suidelines	SUBBAIT DEAD	EDIAT	ION			

PROPOSAL NOT LATER THAN:

Dec. 15 th 2012



# **Incident Report Form**

PIC / DIS Phone: (575) 513-9582

Incident Time: 6 HH 0 MM PM

Location: Devon Energy | US Land | MID-CONTINENT | Permian Basin | PB New Mexico |

Diamond Mound

Incident Number: 26180

**Devon Supervisor:** White, Roy

**Devon Supervisor Phone:** 

**Incident Category:** Environment

**Involvement:** Contractor

Incident Type: Property Damage, Spill

**Regulated By:** 

1. Reporting Information

Person-In-Charge (PIC) / Devon Brooke Owens

Transactions Committee (PTC)

Immediate Supervisor (DIS):

Report Date: 11/7/2012 Report Time: 2 HH 41 MM PM

Name / Title Reporting: Brooke Owens Lease Operator Phone: (575) 513-9582

Name / Title of person that discovered the incident:

Kevin, Truck Driver for Basic Energy

**Incident Date:** 11/6/2012

2. Incident Summary

#### **Incident Statement:**

(Property Damage) At the Dickens 29 Federal 3H location, a contractor backed into a load line, causing it to separate from the front of a produced water tank resulting in a 285bbl produced water spill.

#### **Summary of What Happened?**

(Property Damage)At the Dickens 29 Federal 3H location a contractor arrived on location with a vacuum truck to haul produced water. Upon arrival, the driver placed his safety cone in front of the load line accordingly and used it as a reference point to back his trailer. While backing he didn't realize his trailer was at an angle because it was on his blind side. The drivers trailer struck the load line, separating it from the front of the tank. It caused 285bbls of produced water to spill into the lined containment. The driver immediately contacted dispatch at 6 PM to report the incident who then contacted the Lease Operator for that area. The Lease Operator responded immediately. He then contacted his Foreman and Assistant Foreman to report the spill, before making arrangements for additional trucks to clean up the spill. All 285bbls of produced water was recovered. The Lease Operator then contacted a crew to repair the line and return it to service.

Working Activity: Operations - Field Production

Incident Related To: Driving Behavior Additional Information Attached:

Diagram of	Scene 🔲	Photographs 🗹	Police/Regulator	ry Report		Other 🗹		
3. Contractor	Information				1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			
Contractor Co	Contractor Co. Name: Basic Energy Services							
Address:	Loco Hills NM							
Contact:	Garry Green		Phone:	(575)	677-3113	3		
Title:	Pusher		•					
4. Location		The state of the s	The state of the s					
Location (nar	•	-		SCG#:		•		
State: New M	exico	Area/Blk:		ountry:	Eddy			
County/Paris	-		LSD/Legal Desc					
Rig#:	F	Pipeline:	Well #:	3				
Longitude:			Latitude:					
Nearest Town	ı, (Name, dist	ance and directio	n from incident)	:				
6. Spills and	Air Releases			i i i i i i i i i i i i i i i i i i i				
Spills Cause:	Human Error							
Materials Rele	eased: Oil	Produced Water	✓ Fresh Water	☐ Che	emical 🗌	Other 🗌		
Specify Other	•							
	Re	leased in Bbls (m	3) Re	ecovered	in Bbls (	m3)		
Oil:		0 (0)		C	(0)			
<b>Produced Wa</b>	ter:	285 (45.31138)	•	285 (4	5.31138)			
Fresh Water:		0 (0)		C	(0)			
Chemical:		0 (0)		C	(0)			
Other:		0 (0)		C	(0)			
Size of Affect	ed Area: 2	5x100	Chemical	s Spilled	:			
Equipment:								
Describe Area, Property, and Wildlife impacted:  Dickens 29 3H location with no wildlife impacted								
Immediate Co	oncern:							
Describe Immediate Actions taken: vaccuum trucks were called to clean up the spill								
Reportable to	Regulator: Y	'es	Reserve I	Pits:				
9. Property D								
Plant/Facility		and the second s	Unit:	and the second s	gartelia transportation de la companya de la compa			
<b>Equipment Ty</b>	pe:		Incident Relate	d To:				

## 14. Immediate Indident Investigation

Unsafe Acts and

#### **Unsafe Conditions:**

D	ro	ra	d			_	c	
•	LO	CC	u	u	•	c	5	•

15. Preventive/Corre	ative Actions:	y the residen	
	A control of the cont	and the second s	

Item #	Related To	General Control / Defense	Action Required	Person Responsible	Due Date	Completion Date	Corrective Action Taken
40145	Incident	Engineering / Design / Equipment	We will install additional guard rails to prevent further incident.	White, Roy	1/15/2013		
40146	Incident	Communicatio n	Submit incident report within 48 hrs.	White, Roy	11/8/2012	11/9/2012	
40147	Incident	Communicatio n	Discuss incident at next safety meeting	White, Roy	12/6/2012		
40148	Incident	Training	Basic is going to do more training with their drivers.	Pearson, Deremy	11/8/2012	11/8/2012	Discussed with drivers about slowing down, placing the cones further away from load lines. They are also going to put longer hoses on trucks so they don't need to be so close to load water.

00	2000 - All - m 10080-	@ mim of large amon
TO	Weather/Site	

**Describe Conditions of Ground:** 

65

Dry

**Describe Sea conditions** 

**Wave Height:** 

Direction:

Speed:

**Current Direction:** 

Temperature:

Did the weather affect this

incident?

Wind Speed:

Wind Direction:

**Describe Weather:** Dry

18. Notifications
-------------------

Date	Person/Agency	Time	Phone Number	Fax Number
11/6/2012	Basic Energy Services		575-746-2072	
		•		
11/6/2012	Brooke Owens		575-513-9582	
11/6/2012	Tommy Polly		575-748-5290	
11/6/2012	Roy White		575-513-1741	
11/6/2012	Don Mayberry		575-748-0164	

Incident Advisor: Johnson, Linda

19. Summary of Classes

Incident Type

Property Damage

Spill

Class

Class 1

Class 3