


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**Operator** ☒ Initial Report ☒ Final Report

**Name of Company** COG OPERATING LLC **Contact** Pat Ellis  
**Address** 600 West Illinois Avenue, Midland, TX 79701 **Telephone No.** 432-230-0077  
**Facility Name** Canvasback 13 Federal #2H **Facility Type** Tank Battery

**Surface Owner** Federal **Mineral Owner** **Lease No. (API#)** 30-015-40538



**LOCATION OF RELEASE**

Unit Letter A	Section 13	Township 24S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 14.014 Longitude 103 43.094

**NATURE OF RELEASE**

Type of Release Crude oil	Volume of Release 80bbls	Volume Recovered 75bbls
Source of Release Oil tank	Date and Hour of Occurrence 11/08/2012	Date and Hour of Discovery 11/08/2012 9:45 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD	
By Whom? Josh Russo	Date and Hour 11/12/2012 11:27a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Oil haulers did not pick up their loads of oil at the anticipated time causing the oil tank to overflow at the facility.		
Describe Area Affected and Cleanup Action Taken.* Initially 80bbls were released inside the facility and we were able to recover 75bbls with a vacuum truck. This is a lined tank battery. We have steam cleaned the tanks, catwalk, and liner. Any contaminated gravel has been removed and we have replaced with fresh gravel as needed. This facility has been returned to its prior condition.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josh Russo		Approved by District Supervisor:	
Title: Senior Environmental Coordinator		Signed By: 	
E-mail Address: jrusso@concho.com		Approval Date: NOV 16 2012	
Date: 11/14/2012 Phone: 432-212-2399		Expiration Date:	
Conditions of Approval:		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-1409

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo <jrusso@concho.com>  
**Sent:** Wednesday, November 14, 2012 2:02 PM  
**To:** Bratcher, Mike, EMNRD; Jim Amos office (jamos@blm.gov); Terry Gregston (tgregsto@blm.gov)  
**Subject:** C-141 Initial Report - Canvasback 13 Federal #2H TB  
**Attachments:** CANVASBACK 13 FEDERAL #2H TANK BATTERY -- DATE OF RELEASE -- 11-08-2012.pdf

Please see attached the C-141 Initial / Final Report for a release at the Canvasback 13 Federal #2H TB. This is a lined facility.

Thank you,

### **Joshua Russo**

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

[jrusso@concho.com](mailto:jrusso@concho.com)

*Mailing Address:*

One Concho Center

600 W. Illinios Avenue

Midland, Texas 79701



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.