


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW 123333603

OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>192463</i>	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Big Walt CTB <i>BigWalt 2 St 8</i>	Facility Type	Gathering
Surface Owner	Mineral Owner	Lease No.	

LOCATION OF RELEASE

30-015-33315

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	2	22S	24E					Eddy County, NM

Latitude N 32.42289° Longitude W 104.46129°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	10 bbls of water and 4 bbls of oil	Volume Recovered	0 bbls
Source of Release	Failure in fire tube on west heater treater	Date and Hour of Occurrence	11/12/2012	Date and Hour of Discovery	11/12/2012
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	IF YES, To Whom?	Mike Bratcher-NMOCD and Terry Gregston-BLM		
By Whom?	Christopher Jones	Date and Hour	11/14/2012 @ 8:50 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	IF YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The failure of a fire tube on the west heater treater caused 10 bbls of produced water and 4 bbls of oil to leak inside the firewall. 0 bbls were recovered. The tube was repaired to prevent further leaking.

Describe Area Affected and Cleanup Action Taken.*
The area affected was approximately 35' x 45'. Remediation will be performed in accordance with NMOCD-approved and BLM-approved remediation plans.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Christopher Jones	Approved by District Supervisor	Signed By <i>Mike Bratcher</i>
Title:	HES Specialist	Approval Date	NOV 28 2012
E-mail Address:	Christopher.Jones@oxy.com	Expiration Date:	
Date:	<i>11-26-12</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(575) 628-4121		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: Dec. 28, 2012**

2RP-1425

Bratcher, Mike, EMNRD


From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Monday, November 26, 2012 3:47 PM
To: Bratcher, Mike, EMNRD; tgregsto@blm.gov
Cc: christopher_jones@oxy.com; cbrunson@bbcinternational.com;
kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Inital C-141 Big Walt CTB
Attachments: Initial C-141, signed and sent 11-26-12.pdf

Attached is the initial C-141 for a leak located at the Big Walt CTB in Eddy County, NM on 11/12/2012. Receipt notification via email is greatly appreciated. Please feel free to contact me if you have any questions.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

2-22s-24e




Oil Conservation Division

MapNotes


DrawnBy

11/27/2012 8:08:34 AM



Google earth

miles
km



Oxy BigWalt CTR

BigWalt 2 St #8 015-33315 H-2-225-24E