District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Santa Pe, 1919 67303													
Release Notification and Corrective Action													
nJMW1235328868						OPERATOR							
Name of Company BOPCO, L.P. 260737						Contact Tony Savoie							
						Telephone No. 432-556-8730							
Facility Name: Indian Flats Bass Federal #1 SWD						Facility Typ	e: E&P					<u></u>	
Surface Owner Federal Mineral Owner Fe						ederal			Lease No. LC-067144				
LOCATION							NOF RELEASE APT#30-0/5-24968						
·						·· · · · · · · · · · · · · · · · · · ·			West Line County Eddy				
Latitude_N 32.433905 Longitude W 104.055425_													
NATURE OF RELEASE													
Type of Release: Produced water							• · · · · · · · · · · · · · · · · · ·				Recovered: 70 bbls		
Source of Release: A salt water transfer pump.										Date and Hour of Discovery			
Was Immediate Notice Given?							11/27/12 time unknown 11/27/12 1:00 p.m. If YES, To Whom?						
☐ Yes ☐ No ☐ Not Required						NMOCD emergency #104							
By Whom? Tony Savoie						Date and Hour 11/27/12 2:30 p.m.							
Was a Watercourse Reached?							If VFS Volume Impacting the Watercours						
☐ Yes ☒ No						RECEIVED							
If a Watercourse was Impacted, Describe Fully.*							DEC 1 7 2012 NMOCD ARTESIA						
Describe Cause of Problem and Remedial Action Taken.* A backpressure valve broke on the pump, water was sprayed outside the containment area on the caliche pad and road at the facility. The valve was replaced.													
Describe Area Affected and Cleanup Action Taken.*The released fluid affected approximately 4,500 sq. ft. area around the pump, lease road and caliche well pad. The free standing fluid was picked up with a vacuum truck. The release is in the same location as previous spills. An air rotary rig was used to determine the vertical extent of the first release. A rig was on location 12/12/12 and advanced 5 soil bores at various locations around the tank battery location, samples were collected to determine vertical extent. A remediation plan will be developed and submitted to the NMOCD. The Site remediation for the produced water will follow the NMOCD guidelines for leaks and spills. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature:	1 on	Zav		Approved by District Supervisor: Signed By Mile Brances									
Printed Nam	e: Tony Sav	oie							1 1,000				
Title: Waste	Mgmt.& Re	emediation Sp	/	DE Approval Da	C 1 8 2012	E	Expiration Date:						
E-mail Addr	ess: TASav	oie@BassPet.		Conditions of Approval:			Attached						

Phone: 432-556-8730

* Attach Additional Sheets If Necessary

Date: 12/17/12

Remediation per OCD Rules & **Guidelines. SUBMIT REMEDIATION** PROPOSAL NOT LATER THAN:

2RP-1457