


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

njmw 1302241995 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Mongo 25 Federal Com #2	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#) 30-015-37164	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	25	24S	28E					Eddy

Latitude 32.19034 Longitude 104.03323

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	45bbbls Oil 5bbbls Produced water	Volume Recovered	44bbbls Oil 4bbbls Produced water
Source of Release	Oil and Produced water tanks	Date and Hour of Occurrence	12/31/2012	Date and Hour of Discovery	12/31/2012 7:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	01/05/2013		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Two small holes were found in the side of the oil tank and one small hole was found in the produced water tank inside the Mongo 25 Federal Com #2 Tank Battery allowing the release of fluid. The tanks will be repaired or replaced.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 50bbbls of produced fluid were released and we were able to recover 48bbbls with a vacuum truck. All fluid that was released was contained inside the lined facility. All free fluid has been recovered and the tanks have been cleaned. Stained gravel has been removed from the facility and replaced with fresh gravel as needed. This facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By
Title:	Senior Environmental Coordinator	Approval Date:	JAN 22 2013
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	01/15/2013	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:
February 22, 2013**

ZRP-1513

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Tuesday, January 15, 2013 1:44 PM
To: Bratcher, Mike, EMNRD; James A Amos (jamos@blm.gov)
Subject: C-141 Initial/Final Report - Mongo 25 Federal Com #2 Tank Battery
Attachments: MONGO 25 FEDERAL COM #2 TANK BATTERY -- DATE OF RELEASE -- 12-31-2012.pdf

Gentlemen,

Please see attached the C-141 Initial/Final report for a release that occurred at our Mongo 25 Federal Com #2 Tank Battery. This release occurred inside the lined facility.

Thank you,

Joshua Russo

Sr. Environmental Coordinator
432.683.7443 (main)
432.685.4381 (direct)
432.212.2399 (cell)
jrusso@concho.com

Mailing Address:

One Concho Center
600 W. Illinios Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Tuesday, January 15, 2013 1:58 PM
To: Joshua Russo
Cc: Bratcher, Mike, EMNRD
Subject: Re: C-141 Initial/Final Report - Mongo 25 Federal Com #2 Tank Battery

Received, Jennifer Van Curen will be the contact. thanks
On Tue, Jan 15, 2013 at 1:43 PM, Joshua Russo <jrusso@concho.com> wrote:

Gentlemen,

Please see attached the C-141 Initial/Final report for a release that occurred at our Mongo 25 Federal Com #2 Tank Battery. This release occurred inside the lined facility.

Thank you,

Joshua Russo

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

jrusso@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Saturday, January 05, 2013 9:17 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo
Subject: Mongo 25 Fed Com #2

Mr. Bratcher:

At approximately 12:00 p.m. on 12/31/2012, a produced fluid release was discovered at the above-referenced facility. An estimated 50 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

32 11.400 104 01.025

Mongo 25 Fed Com #2
Unit H Sec 25 T 24S R 28E
1980 FNL & 374 FEL
Eddy County, NM
NMNM-107373

Travel south on Highway 285 to Pulley Road, Turn east. Travel 3.5 miles, turn left into location.

Michelle Mullins
HSE Field Tech
2407 Pecos Avenue
P.O. Box 1630
Artesia, NM 88211-1630
Phone: (575)746-2010
Cell: (432) 934-1052
mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.