


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJM/1305355697

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #104	Facility Type	SWD

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-25864
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	26S	28E					Eddy

Latitude 32 03.534 Longitude 104 04.612

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	700bbls	Volume Recovered	650bbls
Source of Release	Victaulic clamp on header	Date and Hour of Occurrence	02/06/2013	Date and Hour of Discovery	02/06/2013 11:30 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	02/07/2013 8:05 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A Victaulic clamp failed on the inlet header inside the facility. The inlet header has been replaced with new components that are coated and lined.

Describe Area Affected and Cleanup Action Taken.*

Initially 700bbls were released from the header and we were able to recover 650bbls with vacuum trucks. The release occurred inside the lined facility. The majority of the release was contained inside the walls of the tank battery. All free fluid has been recovered. Contaminated gravel has been removed from inside the facility and we have replaced with fresh gravel as necessary. The facility has been returned to its prior condition. Tetra Tech will sample the spill site area outside of the lined facility to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name:

Josh Russo

Title:

Senior Environmental Coordinator

E-mail Address:

russo@concho.com

Date: 02/18/2013

Phone: 432-212-2399

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Signed By

FEB 22 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule &

Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

March 22, 2013

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1563

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Monday, February 18, 2013 8:59 AM
To: Bratcher, Mike, EMNRD
Cc: Ike Tavaréz (ike.tavaréz@tetrattech.com); Tom Franklin (tom.k.franklin@tetrattech.com); Robert Grubbs
Subject: C-141 Initial Report - SRO SWD #104
Attachments: SRO SWD #104 -- DATE OF RELEASE -- 02-06-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at our SRO SWD #104 in Eddy County. We plan to assess the spill area outside of the facility timely.

Thank you,

Joshua Russo

Sr. Environmental Coordinator
432.683.7443 (main)
432.685.4381 (direct)
432.212.2399 (cell)
jrusso@concho.com

Mailing Address:

One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Thursday, February 07, 2013 7:05 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Robert Grubbs
Subject: SRO 104 SWD-Immediate Notification

Mr. Bratcher:

At approximately 11:30 p.m. on 02/06/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 700 bbls of produced fluid was released. Most of the fluid was contained inside a 40 mil lined facility. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

32 03.534 104 04.612

SRO #104 SWD
Unit F Sec 10 T26S R 28E
1980 FNL 1980 FWL
Eddy County, NM
API 30-015-25864

Travel south on Highway 285 to MM #5, Turn west on White City Road. Travel .5 mile, turn south into location.

Michelle Mullins
HSE Field Tech
2407 Pecos Avenue
P.O. Box 1630
Artesia, NM 88211-1630
Phone: (575)746-2010
Cell: (432) 934-1052
mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.